

Above-Ground Resources Survey Volume II

The Detroit River International Crossing Study



FEBRUARY 2008

**ABOVE-GROUND RESOURCES SURVEY FOR THE DETROIT RIVER INTERNATIONAL
CROSSING (DRIC) STUDY
DETROIT, WAYNE COUNTY, MICHIGAN**

Prepared for

**THE CORRADINO GROUP
200 SOUTH FIFTH STREET, STE 300 NORTH
FIRST TRUST CENTRE
LOUISVILLE, KENTUCKY 40202**

Prepared by

**COMMONWEALTH CULTURAL RESOURCES GROUP, INC.
2530 SPRING ARBOR ROAD
JACKSON, MICHIGAN 49203-3602**

**Rachel Bankowitz, Architectural Historian
Donald J. Weir, Project Manager**

February 2008

R-0681

Volume II

ABSTRACT

Commonwealth Cultural Resources Group, Inc. was contracted by The Corradino Group to document the built environment in and near the proposed Detroit River International Crossing (DRIC) project area in southwest Detroit, Wayne County, Michigan, and to offer National Register of Historic Places (NRHP) evaluations for possible historic resources. The DRIC above-ground resources survey resulted in the documentation of approximately 1,026 pre-1957 primary structures. CCRG recommends that, within the DRIC study area, 20 properties/complexes and three multi-property historic districts are eligible for listing in the NRHP. The remaining architectural resources in the DRIC study area lack significance and/or integrity and are not recommended eligible for listing in the NRHP.

TABLE OF CONTENTS

Volume I

Abstract ii

Illustrations v

List of Tables xiii

1.0 INTRODUCTION 1-1

1.1 Purpose of Analysis and Background 1-1

1.1.1 Historical Summary and Study Area Description 1-1

1.1.2 Survey Coverage 1-3

1.1.3 Summary Survey Results 1-4

1.1.4 Report Content 1-6

1.2 Historic Background 1-6

1.2.1 Native American Settlement in Detroit 1-6

1.2.2 European Settlement and Rural Land Use 1-12

1.3 Historic Contexts 1-18

1.3.1 Transportation 1-18

1.3.2 Industry 1-24

1.3.3 Social History and Lifeways 1-41

1.3.4 Education 1-54

1.3.5 Ethnic Heritage 1-57

1.4 Architectural Contexts 1-70

1.4.1 Residential Forms and Styles 1-71

1.4.2 Public Building Styles 1-87

1.5 Designated Historic Properties 1-93

1.5.1 National Register of Historic Places Criteria of Evaluation 1-95

1.5.2 National and State Listed Historic Structures and Districts 1-95

1.5.3 State Register of Historic Sites Structures and Districts 1-96

1.5.4 Locally Designated Structures and Districts 1-100

2.0 METHODS 2-1

2.1 Pre-Field Research 2-1

2.2 Above-Ground Resources Area of Potential Effects Definition and Tier Descriptions 2-3

2.2.1 Tier 1 2-3

2.2.2 Tier 2 2-3

2.2.3 Tier 3 2-4

2.3 Field Methods 2-4

3.0	FINDINGS.....	3-1
3.1	Above-Ground Resources Descriptions.....	3-1
3.1.1	Tier 1	3-1
3.1.2	Tier 2.....	3-6
3.1.3	Tier 3.....	3-13
3.2	National Register of Historic Places Assessments.....	3-13
3.2.1	Recommended NRHP-Eligible Buildings and Complexes.....	3-14
3.2.2	Proposed Multiple-Property Historic Districts	3-86
3.3	Conclusions and Recommendations	3-140
4.0	REFERENCES	4-1

Glossary

Volume II

Appendix A.	Tables of Above-Ground Resources
Appendix B.	Aerial Photo Maps
Appendix C.	Recommended National Register of Historic Places Resources Images
Appendix D.	Table of Contributing Resources in All Proposed Districts

ILLUSTRATIONS

Figure 1.0-1	Detroit River International Crossing Above-Ground Resources Project Location.....	1-2
Figure 1.0-2	Previously Recorded and NRHP-Recommended Historic Resources in and Near the DRIC APE.....	1-5
Figure 1.2.1-1	Detroit Region Native American and French Settlements in ca. 1735	1-7
Figure 1.2.1-2	Native American and French Settlements on the Detroit River in 1749.....	1-8
Figure 1.2.1-3	Native American and French Settlements on the Detroit River in 1763.....	1-9
Figure 1.2.1-4	Native American and French Settlements on the Detroit River, ca. 1770.....	1-10
Figure 1.2.1-5	French Farms along the Detroit River, 1796.....	1-11
Figure 1.2.1-6	Claims in 1776.....	1-13
Figure 1.2.2-1	DRIC Project Vicinity Private Claims, 1810.....	1-14
Figure 1.2.2-2	Askin’s Springwells Tract, 1796.....	1-16
Figure 1.2.2-3	DRIC Project Vicinity, 1813.....	1-17
Figure 1.2.2-4	Delray Hungarian Settlement, 1904.....	1-19
Figure 1.2.2-5	Village of Delray, ca. 1897	1-20
Figure 1.2.2-6	Delray Area, ca. 1910	1-21
Figure 1.3.1-1	Detroit Metropolitan Roadways, 1934.....	1-25
Figure 1.3.1-2	Detroit Terminals, 1936.....	1-26
Figure 1.3.1-3	Detroit Truck Routes, 1936.....	1-27
Figure 1.3.2-1	Waterbury and Detroit Copper Company, 1850	1-29
Figure 1.3.2-2	Detroit Copper and Brass Rolling Mills, 1888	1-31
Figure 1.3.2-3	Michigan Carbon Works Buffalo Bone Stockpile, 1895	1-32
Figure 1.3.2-4	Area Industrialization, 1940.....	1-34

Figure 1.3.2-5	Detroit Industrial Zones, 1947	1-39
Figure 1.3.2-6	Detroit Region Industrial Corridors, 1968	1-40
Figure 1.3.3-1	Detroit Age Graded Housing, 1940	1-45
Figure 1.3.3-2	International Exposition, 1889.....	1-48
Figure 1.3.3-3	International Exposition, 1889.....	1-48
Figure 1.4.1-1	Gable Front House, 520 Harrington Street	1-72
Figure 1.4.1-2	Two and One-Half-Story Gable Front House, 5645 Anthon Street.....	1-72
Figure 1.4.1-3	Side Gable House, 810 Casgrain Street	1-73
Figure 1.4.1-4	Cross Gable House, 835 North Wheelock Street.....	1-73
Figure 1.4.1-5	T-Plan House, 520 Post Street	1-75
Figure 1.4.1-6	Gabled Ell House, 710 South Green Street.....	1-75
Figure 1.4.1-7	Foursquare House, 7124 West Lafayette Boulevard.....	1-77
Figure 1.4.1-8	Rowhouse, 8032-8040 Witt Street	1-77
Figure 1.4.1-9	Two-Family Flat, 730 Harrington Street.....	1-78
Figure 1.4.1-10	Duplex, 6319-6321 West Lafayette Boulevard.....	1-78
Figure 1.4.1-11	Fourplexes, 1048-1050 and 1058-1060 North Waterman Street	1-80
Figure 1.4.1-12	Queen Anne Style House, 1011-1017 North Morrell Street	1-80
Figure 1.4.1-13	Colonial Revival Style House, 803-805 Casgrain Street	1-82
Figure 1.4.1-14	Dutch Colonial Revival Style House, 1033 North Livernois Avenue	1-82
Figure 1.4.1-15	Tudor Revival Style House, 1037 North Green Street.....	1-83
Figure 1.4.1-16	Side Gable Bungalow, 1003 North Waterman Street.....	1-83
Figure 1.4.1-17	Hipped Roof Bungalow, 815 Glinnan Street	1-85
Figure 1.4.1-18	Mediterranean Style Apartment Building, 760 Campbell Street	1-85
Figure 1.4.1-19	Minimal Traditional Style House, 521 South Crawford Street.....	1-86
Figure 1.4.2-1	Vernacular Commercial Building, 7700 West Jefferson Avenue	1-88

Figure 1.4.2-2	Building with Baroque Detail, 7140 West Fort Street	1-88
Figure 1.4.2-3	Neoclassical Building, 5705 West Fort Street	1-89
Figure 1.4.2-4	Georgian Revival Style Commercial Building, Former Detroit Copper and Brass Rolling Mills Office, 174 South Clark Street	1-89
Figure 1.4.2-5	Georgian Revival Style Ecclesiastical Building, 844 South Harbaugh Street	1-91
Figure 1.4.2-6	Romanesque Revival Style Church, 844 South Harbaugh Street	1-91
Figure 1.4.2-7	Late Gothic Revival Style Church, 8423 South Street.....	1-92
Figure 1.4.2-8	Collegiate Gothic Style Building, 6921 West Fort Street	1-92
Figure 1.4.2-9	Detroit Union Produce Terminal, 7210 West Fort Street	1-94
Figure 1.5.2-1	Map of Fort Wayne	1-97
Figure 1.5.2-2	Officer’s Row, Fort Wayne.....	1-98
Figure 1.5.2-3	Frank Beard School, 840 North Waterman Street	1-99
Figure 1.5.3-1	Detroit Copper and Brass Rolling Mills Historic Marker	1-101
Figure 1.5.4-1	Hubbard Farms Historic District.....	1-103
Figure 1.5.4-2a	McMillan School (January 2008.....	1-104
Figure 1.5.4-2b	McMillan School (2007).....	1-104
Figure 2.1-1	Military Streets Study Area and Hubbard Farms Historic District Locations.....	2-2
Figure 3.1.1-1	Streetscape of Houses along the West Side of North Casgrain Street	3-2
Figure 3.1.1-2	6219-6123 West Lafayette Boulevard	3-2
Figure 3.1.1-3	6155 West Fort Street	3-5
Figure 3.1.1-4	5700 West Fort Street	3-5
Figure 3.1.1-5	4838 West Jefferson Avenue	3-7
Figure 3.1.2-1	870 Glinnan Street	3-9
Figure 3.1.2-2	1039 North Crawford Street.....	3-9
Figure 3.1.2-3	7921 South Street.....	3-11

Figure 3.1.2-4	758 Anderson Street.....	3-11
Figure 3.1.2-5	Detroit Harbor Terminal Building	3-12
Figure 3.1.2-6	7700 West Jefferson Avenue	3-12
Figure 3.2.1-1	Detroit Union Produce Terminal.....	3-15
Figure 3.2.1-2	Detroit Union Produce Terminal, 1950.....	3-16
Figure 3.2.1-3	Michigan Bell Telephone Vinewood Dial Office Building	3-19
Figure 3.2.1-4	Michigan Bell Telephone Vinewood Dial Office Building, 1992	3-20
Figure 3.2.1-5	Fort Street/Green Street Detroit Police Station.....	3-22
Figure 3.2.1-6	Fort Street/Green Street Detroit Police Station, 1950.....	3-23
Figure 3.2.1-7	Findlater Masonic Temple/Salon El Bosque	3-26
Figure 3.2.1-8	Findlater Masonic Temple/Salon El Bosque, 1950.....	3-27
Figure 3.2.1-9	Southwestern High School.....	3-29
Figure 3.2.1-10	Southwestern High School, 1992.....	3-30
Figure 3.2.1-11	Olivet Presbyterian/Old Landmark Church of God in Christ	3-33
Figure 3.2.1-12	Olivet Presbyterian/Old Landmark Church of God in Christ, 1950	3-34
Figure 3.2.1-13	Detroit Savings Bank/George International Building.....	3-36
Figure 3.2.1-14	Detroit Savings Bank/George International Building, 1950.....	3-37
Figure 3.2.1-15	Berwalt Manor Apartment Building	3-39
Figure 3.2.1-16	Berwalt Manor Apartment Building, 1950	3-40
Figure 3.2.1-17	Roberts Brass Manufacturing Company Building	3-42
Figure 3.2.1-18	Roberts Brass Manufacturing Company Building, 1950	3-43
Figure 3.2.1-19	Military Avenue Evangelical Presbyterian Church	3-45
Figure 3.2.1-20	Military Avenue Evangelical Presbyterian Church Parsonage	3-45
Figure 3.2.1-21	Military Avenue Evangelical Presbyterian Church and Parsonage, 1992	3-46
Figure 3.2.1-22	St. Paul AME Church	3-49

Figure 3.2.1-23	St. Paul AME Church, 1950	3-50
Figure 3.2.1-24	Kovacs Bar.....	3-52
Figure 3.2.1-25	Rear of Kovacs Bar.....	3-52
Figure 3.2.1-26	Kovacs Bar, 1992.....	3-53
Figure 3.2.1-27	Motz’s Burgers.....	3-56
Figure 3.2.1-28	Motz’s Burgers, 1992.....	3-57
Figure 3.2.1-29	Detroit Copper and Brass Rolling Mills Complex.....	3-59
Figure 3.2.1-30	Detroit Copper and Brass Rolling Mills Complex, 1944.....	3-60
Figure 3.2.1-31	Mistersky Power Station Complex/City of Detroit Public Lighting Commission	3-63
Figure 3.2.1-32	Mistersky Power Station Complex/City of Detroit Public Lighting Commission, 1944	3-64
Figure 3.2.1-33	Detroit Fire Department Engine Company 29	3-66
Figure 3.2.1-34	Detroit Fire Department Engine Company 29, 1992	3-67
Figure 3.2.1-35	Detroit Harbor Terminal Building	3-69
Figure 3.2.1-36	Former Army Warehouse	3-69
Figure 3.2.1-37	Detroit Harbor Terminal Building, 1950	3-70
Figure 3.2.1-38	Holy Cross Hungarian Roman Catholic Church Complex	3-74
Figure 3.2.1-39	Holy Cross Roman Catholic Church Complex, 1992	3-75
Figure 3.2.1-40	Szent. Janos Gor Kath. Magyar Templom/Jehovah Jireh Church	3-79
Figure 3.2.1-41	Szent. Janos Gor Kath. Magyar Templom/Jehovah Jireh Church, 1992	3-80
Figure 3.2.1-42	St. John Cantius Polish Catholic Church Complex.....	3-83
Figure 3.2.1-43	St. John Cantius Polish Catholic Church Complex, 1992.....	3-84
Figure 3.2.2-1	West Lafayette Boulevard Rowhouse District, 1950.....	3-87
Figure 3.2.2-2	Streetscape of West Lafayette Boulevard, View Northeast	3-89
Figure 3.2.2-3	The Hull Building	3-90

Figure 3.2.2-4	The Olive Building	3-91
Figure 3.2.2-5	The Florence Building	3-92
Figure 3.2.2-6	Proposed Delray Community Historic District and the Delray Commercial Historic District.....	3-94
Figure 3.2.2-7	Streetscape, West Side of West End Avenue, View Southwest from Melville Street.....	3-95
Figure 3.2.2-8	Streetscape, South Side of Melville Street, View Southwest from the North Side of Road.....	3-95
Figure 3.2.2-9	Streetscape, North Side of South Street, View Northwest from Yale Street.....	3-97
Figure 3.2.2-10	Streetscape, North Side of Vanderbilt Street, View Northeast from Yale Street.....	3-97
Figure 3.2.2-11	Streetscape of the Front of the New Greater Love Missionary Baptist Church, 8151 Thaddeus Street.....	3-98
Figure 3.2.2-12	Streetscape, South Side of South Street, View Southwest from West End Avenue.....	3-99
Figure 3.2.2-13	Streetscape, North Side of South Street, View Northwest from the South Side of Road.....	3-99
Figure 3.2.2-14a	McMillan School, 615 South West End Avenue (January 2008)	3-103
Figure 3.2.2-14b	McMillan School, 615 South West End Avenue (2007).....	3-103
Figure 3.2.2-15	Former Evangelical Lutheran Concordia School (presently the Sweet Communion Baptist Church), 8419 Vanderbilt Street.....	3-104
Figure 3.2.2-16	Former Home of the First Szekely-Magyar Association and Free Magyar Reformed Church (presently the Solvay Church of God in Christ), 8020 Thaddeus Street	3-104
Figure 3.2.2-17	Former Home of the Bridgeport Association Lodge #14 Hungarian Benefit Society, 608/610 West End Avenue.....	3-105
Figure 3.2.2-18	Former Szabo’s Market (presently Mi Tienda), 434 West End Avenue.....	3-105
Figure 3.2.2-19	Former West End Market, 428 West End Avenue.....	3-107
Figure 3.2.2-20	Detroit Edison West End Substation, 8035 South Street.....	3-107
Figure 3.2.2-21	Holy Cross Hungarian Catholic Church Complex, 8423 South Street	3-109

Figure 3.2.2-22	The True Light Church of God in Christ, 8400 Vanderbilt Street.....	3-109
Figure 3.2.2-23	The New Greater Love Missionary Baptist Church, 8151 Thaddeus Street.....	3-110
Figure 3.2.2-24	Streetscape of Dill Place, View Southeast.....	3-110
Figure 3.2.2-25	710 Sloan Street.....	3-113
Figure 3.2.2-26	Streetscape of the New Greater Love Missionary Baptist Church and 710 Sloan Street.....	3-113
Figure 3.2.2-27	Streetscape of Proposed District, North Side of West Jefferson Avenue.....	3-118
Figure 3.2.2-28	Streetscape of Proposed District, South Side of West Jefferson Avenue.....	3-118
Figure 3.2.2-29	Streetscape of 7925-41, 8000-05, 8015-17, 8035, and 8051 West Jefferson Avenue.....	3-119
Figure 3.2.2-30	Streetscape of 8129 and 8149-51 West Jefferson Avenue.....	3-119
Figure 3.2.2-31	Streetscape of 8100, 8112, 8118, and 8128-30 West Jefferson Avenue.....	3-120
Figure 3.2.2-32	Streetscape of 8000-04, 8022, and 8032 West Jefferson Avenue.....	3-120
Figure 3.2.2-33	Streetscape of Planters along West Jefferson Avenue.....	3-122
Figure 3.2.2-34	Delray Angels.....	3-122
Figure 3.2.2-35	Blitz Building, 7925-7941 West Jefferson Avenue, North and East Elevations.....	3-123
Figure 3.2.2-36	Blitz Building, 7925-7941 West Jefferson Avenue, Façade.....	3-123
Figure 3.2.2-37	8000-8004 West Jefferson Avenue, Facade.....	3-124
Figure 3.2.2-38	8000-8004 West Jefferson Avenue, South and West Elevations.....	3-124
Figure 3.2.2-39	Peninsular State Bank Building/Magyar Haz, 8001-8005 West Jefferson Avenue, North and East Elevations.....	3-125
Figure 3.2.2-40	Peninsular State Bank Building/Magyar Haz, 8001-8005 West Jefferson Avenue, Hungarian Club Sign.....	3-125
Figure 3.2.2-41	8015-8017 West Jefferson Avenue, North and West Elevations.....	3-127
Figure 3.2.2-42	Datestone, 8015-8017 West Jefferson Avenue.....	3-127
Figure 3.2.2-43	Delray Theater, 8022 West Jefferson Avenue, Facade.....	3-128

Figure 3.2.2-44	Delray Theater, 8022 West Jefferson Avenue, South and West Elevations	3-128
Figure 3.2.2-45	Delray Café, 8032 West Jefferson Avenue, South and West Elevations.....	3-130
Figure 3.2.2-46	Mural, Delray Café, 8032 West Jefferson Avenue, West Elevation.....	3-130
Figure 3.2.2-47	8035 West Jefferson Avenue, Facade	3-131
Figure 3.2.2-48	8035 West Jefferson Avenue, North and East Elevations.....	3-131
Figure 3.2.2-49	8051 West Jefferson Avenue, North and East Elevations.....	3-132
Figure 3.2.2-50	8100 West Jefferson Avenue, Facade	3-132
Figure 3.2.2-51	8100 West Jefferson Avenue, South and East Elevations.....	3-133
Figure 3.2.2-52	Former Clock, 8100 West Jefferson Avenue, Facade.....	3-133
Figure 3.2.2-53	8112 West Jefferson Avenue, Facade	3-135
Figure 3.2.2-54	8118 West Jefferson Avenue, Facade	3-135
Figure 3.2.2-55	Gunsberg Building, 8128-8130 West Jefferson Avenue, South and East Elevations.....	3-136
Figure 3.2.2-56	Gunsberg Building, 8128-8130 West Jefferson Avenue, South and West Elevations	3-136
Figure 3.2.2-57	Gunsberg Nameplate, 8128-8130 West Jefferson Avenue, Facade.....	3-137
Figure 3.2.2-58	8129 West Jefferson Avenue, Facade	3-137
Figure 3.2.2-59	8129 West Jefferson Avenue, North and East Elevations.....	3-138
Figure 3.2.2-60	8149-8151 West Jefferson Avenue, Facade.....	3-138
Figure 3.2.2-61	8149-8151 West Jefferson Avenue, North and East Elevations	3-139

LIST OF TABLES

Table 1.1.3-1	Above-Ground Resources Recommended Eligible for Listing in the NRHP	1-4
Table 1.5-1	Previously Listed Historic Resources within the DRIC Study Area.....	1-95
Table 2.1-1	Properties within the DRIC APE Recommended NRHP Eligible by the Detroit Historic Designation Advisory Board.....	2-4
Table 3.1.1-1	Approximate Number of Pre-1957 Above-Ground Resources, Tier 1	3-1
Table 3.1.2-1	Approximate Number of Pre-1957 Above-Ground Resources, Tier 2	3-8
Table 3.2-1	Above-Ground Resources Recommended Eligible for Listing in the NRHP	3-13
Table 3.3-1	Approximate Number of Pre-1957 Above-Ground Resources, Tiers 1 and 2	3-140
Table 3.3-2	Above-Ground Properties Recommended Eligible for Listing in the National Register of Historic Places	3-141
Table 3.3-3	Approximate Number of Contributing Resources, Proposed Delray Community Historic District.....	3-142

APPENDIX A

TABLES OF ABOVE-GROUND RESOURCES

This appendix contains documentation for all resources surveyed during the DRIC above-ground resources investigation. Tables for resources in Tiers 1 and 2 contain photographs, addresses, property type, approximate construction date, style, and NRHP evaluation. Documentation for Tier 3 consists of streetscape photographs of resources. The tables for Tiers 1 and 2 are arranged alphabetically by street name within each tier. The Tier 3 photographs are arranged to illustrate the character of the neighborhoods and are not arranged in any geographic order.

Tier 1

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	74	115	American Way	Commercial	Ca. 1946	Vernacular	Multiple additions, modern replacement materials, altered windows and doors.	N	N
	1	72	150	American Way	Commercial	Ca. 1954	Vernacular	Multiple additions, modern replacement materials, altered windows and doors, some window openings filled with concrete block.	N	N
	1	74	177	American Way	House	Ca. 1915	Bungalow	Enclosed front porch, vinyl siding, glass block infill, typical of buildings in the area and therefore lacks architectural distinction.	N	N
	1	74	183	American Way	House	Ca. 1915	Bungalow	Altered front porch, vinyl replacement siding, replacement windows. Typical of buildings in the area and therefore lacks architectural distinction.	N	N
	1	74	189	American Way	House	Ca. 1915	Bungalow	Glassblock window additions, vinyl siding, replacement windows. Typical of buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	74	195	American Way	House	Ca. 1915	Bungalow	Vinyl replacement siding, glass block window additions, replacement windows. Lacks architectural distinction.	N	N
	1	74	229	American Way	Two-Family Flat	Ca. 1915	Foursquare	Enclosed front porch, vinyl siding, glass block infill, typical of buildings in the area and therefore lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	26	5624	Anthon St.	Commercial	Ca. 1957	Vernacular	Commercial storage building, modern replacement materials.	N	N
	1	26	5630	Anthon St.	House	Ca. 1895	T-Plan	Vinyl replacement siding, replaced windows, altered porch areas. Typical of many buildings in the area and therefore lacks architectural distinction.	N	N
	1	25	5637	Anthon St.	House	Ca. 1910	Gable Front	Aluminum siding, permastone veneer, modified front porch. Lacks architectural distinction.	N	N
	1	25	5645	Anthon St.	House	Ca. 1880	Gable Front	Retains many original features although has Insulbrick siding. Lacks architectural distinction.	N	N
	1	25	5651	Anthon St.	House	Ca. 1900	Cross Gable	Vinyl replacement siding, replaced windows, altered porch area. Similar to other buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	25	5655	Anthon St.	House	Ca. 1900	Cross Gable	Permastone veneer, vinyl replacement siding. Lacks architectural distinction.	N	N
	1	25	5667	Anthon St.	House	Ca. 1900	Cross Gable	Replaced picture window, vinyl replacement siding, altered entry porch. Similar to many buildings in the area. Lacks architectural distinction.	N	N
	1	25	5671	Anthon St.	House	Ca. 1902	Gable Front	Aluminum replacement siding, altered front porch, some replacement windows. Similar to many buildings in the area. Lacks architectural distinction.	N	N
	1	25	5679	Anthon St.	House	Ca. 1900	Gable Front	Vinyl replacement siding. Similar to many buildings in the area. Lacks architectural distinction.	N	N
	1	29	5838	Anthon St.	House	Ca. 1916	Gable Front	Asbestos shingles wall cladding, some windows covered with metal roller shades. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	29	5876	Anthon St.	House	Ca. 1900	T-Plan	Altered porch, vinyl siding, replacement windows. Typical of many buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	70	720	S. Beard St.	Rowhouse	Ca. 1914	Vernacular	Some replaced windows and doors, altered porch areas. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	143	809	N. Beard St.	House	Ca. 1915	Bungalow	FIRE DAMAGED PER FIELD VISIT JANUARY 2008. Some replacement windows, asphalt shingles added to dormer. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	145	810	N. Beard St.	Lafayette Manor Apartments	Ca. 1915	Tudor Revival elements	Not architecturally or historically distinctive. Façade doorway opening altered with glass block. Replaced windows.	N	N
	1	143	815	N. Beard St.	House	Ca. 1915	Bungalow	Replaced windows and doors, asphalt shingle siding on the dormer walls. Typical of buildings in the area. Lacks architectural distinction.	N	N
	1	145	836	N. Beard St.	House	Ca. 1910	Colonial Revival	Replaced windows, combination of stucco and clapboard siding. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	145	840	N. Beard St.	House	Ca. 1910	Colonial Revival	Insulbrick siding, replaced windows, altered front porch, glass block infill windows. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	145	846	N. Beard St.	House	Ca. 1905	Princess Anne	Enclosed front porch, replaced doors, most original windows. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	145	850	N. Beard St.	House	Ca. 1910	Foursquare	Replaced windows and doors, some vinyl replacement siding. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	145	856	N. Beard St.	Commercial Ruins	Unknown	Ruins	Former commercial structure damaged by fire.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	53	6357	Buelow Ct.	Two-Family Flat	Ca. 1915	Foursquare	Wood shingle siding, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluations	
									Individual	District
	1	24	106	N. Campbell St.	Industrial	Ca. 1912	Vernacular	Reinforced concrete and brick construction. Original openings present but covered. Typical example of early 20th century industrial building in the area. Lacks architectural distinction.	N	N
	1	31	150	S. Campbell St.	House	Ca. 1902	Dutch Colonial Revival	Common architectural style in the area. Setting has been compromised by adjacent commercial enterprise. Aesthetically intact, but not architecturally or historically distinctive.	N	N
	1	31	156	S. Campbell St.	House	Ca. 1910	Gable Front	Replacement windows and porch alterations. House is typical of those in the area. Lacks architectural distinction.	N	N
	1	31	170 (Front)	S. Campbell St.	House	Ca. 1912	Cross Gable	Vinyl siding, replacement windows, and altered porch. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	31	170 (Rear)	S. Campbell St.	House	Ca. 1930	Vernacular	Vinyl siding and altered front porch. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluations	
									Individual	District
	1	26	300	N. Campbell St. (faces Anthon St.)	Two-Family Flat	Ca. 1915	Vernacular	Vinyl siding and replacement windows. The building lacks architectural distinction.	N	N
	1	22	317	S. Campbell St.	House	Ca. 1910	Gable Front	Vinly siding and replacement windows. Enclosed front porch. The building lacks architectural distinction.	N	N
	1	22	321	S. Campbell St.	House	Ca. 1910	Gabled Ell	Vinly siding and replacement windows. Typical example of the houses in the area. Lacks architectural distinction.	N	N
	1	29	321	N. Campbell St.	House	Ca. 1890	Gabled Ell	Aluminum siding, replaced windows, and altered porch. Typical example of the houses in the area. Lacks architectural distinction.	N	N
	1	29	331	S. Campbell St.	House	Ca. 1881	T-Plan	Insulbrick siding and alterations to the side porch entry. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluations	
									Individual	District
	1	29	347	N. Campbell St.	House	Ca. 1910	Dutch Colonial Revival	Fire damage.	N	N
	1	29	352 (Rear of 321)	N. Campbell St.	House	Ca. 1920	Gable-Front	Aluminum siding over earlier Insulbrick siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	21	425	S. Campbell St.	Industrial	Ca. 1922	Vernacular	Modest industrial facility with replacement overhead door. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	33	444	S. Campbell St.	Industrial	Ca. 1950	Vernacular	Modern replacement materials, multiple additions. Lacks architectural distinction.	N	N
	1	20	521	S. Campbell St.	Industrial	Ca. 1957	Vernacular	Modern replacement materials, multiple additions. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluations	
									Individual	District
	1	27	722	N. Campbell St.	House	Ca. 1890	Gabled Ell	Vinyl siding, some replaced windows, and a modified entry porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	725	N. Campbell St.	Two-Family Flat	Ca. 1910	Vernacular	Not architecturally or historically distinctive. Cornice removed, front porch appears to be reconstructed, first-story façade doorway opening has been altered.	N	N
	1	27	730	N. Campbell St.	House	Ca. 1908	Cross Gable	Modern replacement siding, replaced windows, and altered front porch. Typical example of a building in the area. Lacks architectural distinction.	N	N
	1	28	731	N. Campbell St.	Two-Family Flat	Ca. 1910	Colonial Revival	Most windows replaced and the front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	741	N. Campbell St.	Two-Family Flat	Ca. 1895	Colonial Revival	Vinyl siding, modified front porch, and some replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluations	
									Individual	District
	1	28	749	N. Campbell St.	Two-Family Flat	Ca. 1902	Foursquare	Combination of aluminum and vinyl replacement siding, mix of original and replacement windows, altered front porch area. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	757	N. Campbell St.	House	Ca. 1890	Gable-Front	Coursed asbestos shingle siding, altered front porch, most windows replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	27	760	N. Campbell St.	Berwalt Manor Apartment Building	Ca. 1929	Mediterranean	Unusual building style in area. Some windows replaced but otherwise retains a high level of historic integrity.	Y	N
	1	28	763	N. Campbell St.	House	Ca. 1907	Gable Front	Exterior walls are clad with a combination of aluminum siding and permastone veneer, most windows replaced, and the front porch altered. Lacks architectural distinction.	N	N
	1	157	1004	N. Campbell St.	House	Ca. 1890	Queen Anne	Vinyl replacement siding, replaced windows and doors, rear addition. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluations	
									Individual	District
	1	156	1007	N. Campbell St.	House	Ca. 1890	T-Plan	Aluminum replacement siding, replaced windows, and altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	157	1008_1010	N. Campbell St.	Two-Family Flat	Ca. 1915	Foursquare	Most original doors and windows intact. Altered second-story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	156	1015	N. Campbell St.	House	Ca. 1905	Gabled Ell	Aluminum siding, permastone veneer, and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	157	1018	N. Campbell St.	House	Ca. 1905	Colonial Revival	Aluminum siding, replacement windows, modified front porch with permastone veneer on the foundation. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	59	728	S. Casgrain St.	Two-Family Flat	Ca. 1910	Foursquare	Altered porches, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	803_805	N. Casgrain St.	Two-Family Flat	Ca. 1905	Colonial Revival	Rear porch addition, mix of original and replaced windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	148	804	N. Casgrain St.	House	Ca. 1910	Foursquare	Vinyl replacement siding, front porch altered, replaced windows and doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	148	810	N. Casgrain St.	House	Ca. 1905	Colonial Revival	Largely intact residence. Typical of buildings in the area. Lacks architectural distinction.	N	N
	1	147	811	N. Casgrain St.	House	Ca. 1910	Foursquare	Some windows replaced and glass block infill on basement level windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	148	816_818	N. Casgrain St.	Two-Family Flat	Ca. 1910	Foursquare	Original front doors, original windows intact, modified front porches. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	147	821	N. Casgrain St.	House	Ca. 1910	Bungalow	Modern replacement siding on the dormer walls, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	148	824	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Appears to retain a high level of historic integrity with the exception of the glass block infill in the basement windows. Typical of buildings in the area. Lacks architectural distinction.	N	N
	1	147	829	N. Casgrain St.	House	Ca. 1905	Colonial Revival	Appears to retain a high level of historic integrity. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	147	833_835	N. Casgrain St.	Two-Family Flat	Ca. 1910	Gable Front	Porches altered, most original windows and doors intact. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	148	834_836	N. Casgrain St.	Two-Family Flat	Ca. 1910	Foursquare	Some vinyl replacement siding, altered fenestration, most windows and doors replaced, modified porches. Lacks architectural distinction.	N	N
	1	148	840	N. Casgrain St.	House	Ca. 1910	Foursquare	Appears to retain a high level of historic integrity. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	147	841	N. Casgrain St.	House	Ca. 1910	Foursquare	Aluminum replacement siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	148	846	N. Casgrain St.	House	Ca. 1905	Colonial Revival	Altered front porch. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	147	847	N. Casgrain St.	House	Ca. 1910	Foursquare	Enclosed front porch is clad with vinyl siding. New windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	CCRG 5	1000_1002	N. Casgrain St.	Two-Family Flat	Ca. 1905	Colonial Revival	Altered front porch, including the removal of the second story balcony. The house also has replacement windows and doors. Lacks architectural distinction.	N	N
	1	CCRG 4	1015	N. Casgrain St.	House	Ca. 1915	Bungalow	Aluminum replacement siding, modified front porch, mix of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	37b	156	S. Cavalry St.	Two-Family Flat	Ca. 1915	Foursquare	DEMOLISHED PER FIELD VISIT SEPTEMBER 2007. Altered window openings, replaced windows and doors, modified porch areas. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	37b	298	S. Cavalry St.	Ruins	Ca. 1915	Unknown	DEMOLISHED PER FIELD VISIT SEPTEMBER 2007. Fire Ruins.	N	N
	1	32	301	S. Cavalry St.	Industrial	Ca. 1950	Vernacular	Commercial storage building with modern replacement materials. Lacks architectural distinction.	N	N
	1	39	303	S. Cavalry St.	Ruins	Ca. 1915	Foursquare	DEMOLISHED PER FIELD VISIT SEPTEMBER 2007. Fire Ruins.	N	N
	1	39	317	S. Cavalry St.	Two-Family Flat	Ca. 1915	Foursquare	Vinyl replacement siding, altered front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	37b	318	S. Cavalry St.	House	Ca. 1910	Gable Front	Insulbrick siding and a modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37b	322	S. Cavalry St.	House	Ca. 1909	Gable Front	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Replaced windows and altered front porch. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	29	334	S. Cavalry St.	House	Ca. 1910	Gable Front	Vinyl siding, enclosed front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	29	340	S. Cavalry St.	House	Ca. 1910	Gable Front	Vinyl siding, some replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	29	346	S. Cavalry St.	House	Ca. 1910	Gable Front	Insulbrick siding. Typical of houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	37b	348	S. Cavalry St.	House	Ca. 1909	Gable Front	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Aluminum siding, original windows and front door, altered front porch. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	37b	356	S. Cavalry St.	House	Ca. 1909	Gable Front	Aluminum siding, covered architectural details, and altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37a	418	S. Cavalry St.	Ruins	Ca. 1902	Unknown	DEMOLISHED PER FIELD VISIT SEPTEMBER 2007. Fire ruins.	N	N
	1	37a	462	S. Cavalry St.	House	Ca. 1910	Gable Front	Aluminum replacement siding and some replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	40	761	S. Cavalry St.	Two-Family Flat	Ca. 1915	Foursquare	Some replaced windows, modified front porch, glass block window infill. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	28	762	S. Cavalry St.	House	Ca. 1905	T-Plan	Vinyl siding, modified front porch, and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	768	S. Cavalry St.	House	Ca. 1910	Gable Front	Vinyl siding and altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	156	1015	N. Cavalry St.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch, and replacement windows. The house is typical of those in the area. Lacks architectural distinction.	N	N
	1	156	1016	N. Cavalry St.	House	Ca. 1910	Cross Gable	Aluminum and permastone siding, altered fenestration, glass block window infill, modified front porch, replacement windows. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	155	1021	N. Cavalry St.	House	Ca. 1910	Gable Front	Aluminum siding, permastone veneer, modified front porch, added shed roof dormer. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	140	814	N. Central St.	House	Ca. 1905	Gabled Ell	Aluminum replacement siding, porch enclosed, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	139	815_817	N. Central St.	Two-Family Flat	Ca. 1905	Colonial Revival	Modern replacement siding clads dormer walls, altered fenestration patter. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	820	N. Central St.	House	Ca. 1905	Gabled Ell	Vinyl replacement siding, original windows appear intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	139	823	N. Central St.	House	Ca. 1905	Colonial Revival	Aluminum replacement siding, altered fenestration pattern on dormer. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	828	N. Central St.	House	Ca. 1905	Gabled Ell	Vinyl replacement siding, mix of original and replacement doors and windows, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	140	836	N. Central St.	Two-Family Flat	Ca. 1910	Foursquare	Good original level of integrity although the porches on each level have been altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	139	839	N. Central St.	House	Ca. 1915	Bungalow	Glass block infill in the basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	840_842	N. Central St.	Two-Family Flat	Ca. 1910	Vernacular	Altered porches, most original windows intact, original cornice appears to have been removed. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	50 A & B	203	S. Crawford St.	Former Fisher Body Plant	Ca. 1910	Vernacular	Mix of modern replacement materials, multiple additions, former headquarters building demolished. Lacks architectural distinction	N	N
	1	56	260	S. Crawford St.	Industrial	Ca. 1920	Vernacular	Mix of modern replacement wall materials. Lacks architectural distinction.	N	N
	1	52	509	S. Crawford St.	House	Ca. 1929	Bungalow	Aluminum replacement siding, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	515	S. Crawford St.	House	Ca. 1928	Bungalow	Fire damage, modified front porch, some windows missing.	N	N
	1	52	521	S. Crawford St.	House	Ca. 1930	Minimal Traditional	Glass block window infill at basement level. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	52	527	S. Crawford St.	House	Ca. 1928	Bungalow	Vinyl siding applied over the side walls of the dormer. Typical of many houses in the area, the building lacks architectural distinction.	N	N
	1	53	605	S. Crawford St.	Commercial/ Residential	Ca. 1929	Vernacular	Many of the original openings infilled with either glass block or T-111. Most remaining windows are replacements. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	53	609	S. Crawford St.	House	Ca. 1929	Bungalow	Mix of replacement and original windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	615_617	S. Crawford St.	Two-Family Flat	Ca. 1927	Foursquare	Many windows are replacements. Alterations to the front porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	627	S. Crawford St.	House	Ca. 1926	Bungalow	Some modern replacement siding, modified front porch, most original windows intact. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	53	633	S. Crawford St.	House	Ca. 1928	Gable Front	Porches altered and some replacement windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	53	639_641	S. Crawford St.	Two-Family Flat	Ca. 1927	Foursquare	Glass block infill in the basement windows, some replacement windows, altered porch areas. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	645	S. Crawford St.	House	Ca. 1928	Bungalow	Well maintained residence with only modest changes made to the front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	651_653	S. Crawford St.	Two-Family Flat	Ca. 1927	Foursquare	Well maintained residence with no visible alterations to the historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	657	S. Crawford St.	House	Ca. 1927	Bungalow	Mix of original and replacement windows, some vinyl siding. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	54	662	S. Crawford St.	Commercial	Ca. 1908	Vernacular	Most windows and doors have been replaced and glass block infills some windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	53	663	S. Crawford St.	Two-Family Flat	Ca. 1927	Foursquare	Most original windows and doors are intact, porches have been modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	669_671	S. Crawford St.	Two-Family Flat	Ca. 1927	Foursquare	Modified porches, most original windows and doors have been replaced. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	53	675	S. Crawford St.	House	Ca. 1927	Foursquare	Replacement windows and doors, modified front porch, vinyl siding. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	53	681	S. Crawford St.	House	Ca. 1927	Foursquare	Replaced windows and doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	53	687	S. Crawford St.	Two-Family Flat	Ca. 1927	Foursquare	Replaced windows and doors, modified porches, vinyl siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	692	S. Crawford St.	House	Ca. 1925	Bungalow	Vinyl siding, most original windows and doors have been replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	695	S. Crawford St.	House	Ca. 1926	Bungalow	House retains a most of its historic materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	53	701	S. Crawford St.	Two-Family Flat	Ca. 1938	Tudor Revival	Replacement windows and doors, infill glass block windows in the lower level. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	806	N. Crawford St.	House	Ca. 1905	Colonial Revival	Aluminum replacement siding, front porch altered, mix of original and replacement windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	148	809	N. Crawford St.	House	Ca. 1905	T-Plan	Aluminum siding, modified porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	810	N. Crawford St.	House	Ca. 1910	Gable Front	Modern replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	148	815	N. Crawford St.	House	Ca. 1910	Gable Front	Aluminum and vinyl replacement siding, permastone veneer, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	816	N. Crawford St.	House	Ca. 1905	T-Plan	Vinyl replacement siding, mix of original and replacement windows, rear addition.	N	N
	1	149	822	N. Crawford St.	House	Ca. 1905	T-Plan	Aluminum siding, modified front porch, some replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	149	828_830	N. Crawford St.	Two-Family Flat	Ca. 1915	Foursquare	Vinyl siding, altered porches, and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	148	833	N. Crawford St.	House	Ca. 1915	Foursquare	Vinyl siding, modified front porch, mix of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	834	N. Crawford St.	House	Ca. 1905	T-Plan	Altered fenestration, replaced windows and doors, vinyl replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	148	839	N. Crawford St.	House	Ca. 1905	T-Plan	Most original windows intact, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	840	N. Crawford St.	House	Ca. 1910	Foursquare	Asbestos shingles, modified front porch, most original windows and doors intact. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	150	1012	N. Crawford St.	House	Ca. 1910	Cross Gable	Vinyl replacement siding, altered porch, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	CCRG 5	1015	N. Crawford St.	House	Ca. 1905	Colonial Revival	Most original windows and doors intact, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	43a	135	S. Dragoon St.	Commercial	Ca. 1950	Vernacular	Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	43a	319	S. Dragoon St.	House	Ca. 1905	Gable-Front	Combination of Insulbrick and vinyl siding, altered front porch, and replacement windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	43a	325	S. Dragoon St.	House	Ca. 1905	Gable Front	Fire damage.	N	N
	1	43a	331	S. Dragoon St.	House	Ca. 1910	Foursquare	Insulbrick siding, altered window openings, and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	42a	350	S. Dragoon St.	Rowhouse	Ca. 1914	Vernacular	Modified porches and replacement windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	43a	367	S. Dragoon St.	House	Ca. 1910	Gable Front	Mix of modern replacement siding materials and some replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43b	399	S. Dragoon St.	House	Ca. 1909	Cross Gable	Insulbrick siding, most original windows and doors intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43b	501	S. Dragoon St.	House	Ca. 1905	Cross Gable	House retains a most of its historic materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	44	536	S. Dragoon St.	Two-Family Flat	Ca. 1913	Foursquare	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Modern replacement siding, permastone veneer, and modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	44	548	S. Dragoon St.	House	Ca. 1905	Gable-Front	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Mix of modern replacement wall coverings, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	41	730	S. Dragoon St.	Two-Family Flat	Ca. 1910	Foursquare	House retains a most of its historic materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	153	840	N. Dragoon St.	Lafayette Lodge No. 177	Ca. 1925	Colonial Revival	Minor alterations to windows and doors, although no changes were made to the size of the fenestration opening. Architecturally distinctive building.	N	N
	1	152	841	N. Dragoon St.	House	Ca. 1905	T-Plan	Insulbrick siding and permastone veneer, modified porch, replaced windows and doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	154	1002_1004	N. Dragoon St.	Two-Family Flat	Ca. 1905	Colonial Revival	With the exception of some changes made to the porches, the building retains a high level of its historic construction material. However, it lacks architectural distinction.	N	N
	1	154	1006_1010	N. Dragoon St.	Duplex	Ca. 1915	Bungalow	Vinyl replacement siding, some replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	154	1020	N. Dragoon St.	House	Ca. 1915	Side Gable	Vinyl replacement siding, modified porches, mix of original and replaced doors and windows. Lacks architectural distinction.	N	N
	1	151	1023	N. Dragoon St.	House	Ca. 1910	Gable Front	Aluminum siding, altered side porch, most original windows and doors intact. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	23	5632	Driggs St.	House	Ca. 1900	Gabled Ell	Mix of replacement wall materials, replaced windows and doors, rear addition, modified front porch. Lacks architectural distinction.	N	N
	1	22	5649	Driggs St.	House	Ca. 1900	Gable Front	Combination of vinyl siding and permastone veneer, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	22	5653	Driggs St.	House	Ca. 1921	Vernacular	Rear addition, mix of original and replacement windows, some replacement siding. Lacks architectural distinction.	N	N
	1	23	5654	Driggs St.	Two-Family Flat	Ca. 1890	Vernacular	Insulbrick siding, modified porches, side garage addition, missing cornice. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	22	5673	Driggs St.	House	Ca. 1900	Gable Front	Insulbrick siding, modified front porch, multiple rear additions, most original windows intact. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	160	1002	N. Ferdinand St.	House	Ca. 1890	Queen Anne	Front porch enclosed, vinyl replacement siding, most windows and doors have been replaced. Lacks architectural distinction.	N	N
	1	160	1008	N. Ferdinand St.	House	Ca. 1905	Colonial Revival	Vinyl replacement siding, altered front porch, mix of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	160	1014	N. Ferdinand St.	House	Ca. 1905	Dutch Colonial Revival	Asbestos wall siding, altered front porch, glass block infill in basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	159	1015_1017	N. Ferdinand St.	Two-Family Flat	Ca. 1905	Colonial Revival	Well maintained residence with no visible alterations to the historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	162	4432	Fisher Freeway W.	House	Ca. 1910	Colonial Revival	Vinyl siding, fenestration altered, replacement windows, and altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	162	4450	Fisher Freeway W.	House	Ca. 1910	Colonial Revival	Insulbrick and vinyl siding, rear dormer addition, fenestration altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	162	4462	Fisher Freeway W.	House	Ca. 1895	Gabled Ell	Combination of non-period wall coverings, side porch addition, entry porch enclosed, fenestration altered. Lacks architectural distinction.	N	N
	1	161	4636	Fisher Freeway W.	House	Ca. 1915	Vernacular	Not architecturally or historically distinctive, some modern replacement materials, replaced windows and doors.	N	N
	1	159	4820	Fisher Freeway W.	Two-Family Flat	Ca. 1910	Colonial Revival	Replaced doors and windows, some vinyl replacement siding, altered porches. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	159	4836	Fisher Freeway W.	Rowhouse	Ca. 1920	Vernacular	Altered front porch, replaced windows and doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	158	5644	Fisher Freeway W.	House	Ca. 1895	Cross Gable	Aluminum replacement siding and altered side entry porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	158	5648	Fisher Freeway W.	House	Ca. 1895	Cross Gable	Aluminum siding, porch enclosed, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	158	5656	Fisher Freeway W.	House	Ca. 1910	Gable Front	Combination of aluminum siding and permastone veneer, alterations to the fenestration pattern and front porch. Lacks architectural distinction.	N	N
	1	158	5660_5664	Fisher Freeway W.	House	Ca. 1910	Dutch Colonial Revival	Vinyl replacement siding, front porch altered, fenestration altered and windows replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	158	5670	Fisher Freeway W.	House	Ca. 1905	Gable Front	Insulbrick siding, permastone veneer, front porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	158	5676	Fisher Freeway W.	House	Ca. 1905	Gable Front	Vinyl replacement siding, front porch altered, Some replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	27	5631_5633	Fisher Freeway W.	Two-Family Flat	Ca. 1911	Cross Gable	Aluminum siding, some replacement windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	157	5636	Fisher Freeway W.	House	Ca. 1910	Dutch Colonial Revival	Vinyl replacement siding, fenestration altered, mix of original and replaced doors and windows, front porch enclosure/addition.	N	N
	1	27	5637	Fisher Freeway W.	House	Ca. 1905	Cross Gable	Vinyl siding on the exterior walls and forming a skirt over the foundation, enclosed porch, altered fenestration. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	27	5645_5647	Fisher Freeway W.	Two-Family Flat	Ca. 1895	T-Plan	Insulbrick wall siding and an enclosed porch. Typical of houses in the area. Lacks architectural distinction.	N	N
	1	27	5651	Fisher Freeway W.	House	Ca. 1905	Cross Gable	Insulbrick and aluminum siding, enclosed porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	27	5657	Fisher Freeway W.	House	Ca. 1905	T-Plan	Insulbrick siding and altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	27	5661	Fisher Freeway W.	House	Ca. 1911	Cross Gable	Front porch addition/enclosure, vinyl replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	5831	Fisher Freeway W.	House	Ca. 1913	Gable Front	Altered front porch, a combination of modern replacement wall claddings, replacement windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	156	5836	Fisher Freeway W.	House	Ca. 1895	T-Plan	Aluminum siding, porch altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	5837	Fisher Freeway W.	House	Ca. 1905	Gable Front	Vinyl replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	156	5840	Fisher Freeway W.	House	Ca. 1895	T-Plan	Aluminum siding, porch modified/enclosed, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	5845	Fisher Freeway W.	House	Ca. 1905	Cross Gable	Fire damage, missing and/or broken windows, modern replacement wall materials. Lacks architectural distinction.	N	N
	1	28	5851	Fisher Freeway W.	House	Ca. 1905	Gable Front	Combination of Insulbrick and Asbestos shingle siding, enclosed front porch, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	156	5862	Fisher Freeway W.	House	Ca. 1895	T-Plan	Vinyl replacement siding, porch modified, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	5865	Fisher Freeway W.	House	Ca. 1910	Foursquare	Retains most of the original construction materials, although the front porch has been altered through enclosure. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	28	5869	Fisher Freeway W.	House	Ca. 1910	Colonial Revival	Vinyl siding, front porch modified, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	156	5870	Fisher Freeway W.	House	Ca. 1895	T-Plan	Vinyl siding, mix of original and replaced doors and windows, porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	28	5873	Fisher Freeway W.	House	Ca. 1915	Bungalow	Front porch altered, concrete parging (vener) over original foundation. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	149	6338	Fisher Freeway W.	House	Ca. 1910	Gable Front	Asbestos shingle wall cladding, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	6346	Fisher Freeway W.	House	Ca. 1910	Gable Front	Combination of asbestos shingles and vinyl siding, enclosed front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	6354	Fisher Freeway W.	Two-Family Flat	Ca. 1910	Gable Front	Vinyl siding, porches altered, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	6360	Fisher Freeway W.	House	Ca. 1910	Gable Front	Vinyl siding, front porch modified, fenestration altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	9a	4735	W. Fort St.	Greater Apostolic Faith Temple	Ca. 1957	Vernacular	Modern materials, additions. Lacks architectural distinction.	N	N
	1	14a	4833	W. Fort St.	Commercial	Ca. 1917	Vernacular	Storefront and second story fenestration patterns altered. Original openings filled with brick and concrete block or plywood. Lacks architectural distinction.	N	N
	1	14a	4847	W. Fort St.	Commercial	Ca. 1910	Vernacular	Both storefront and second story fenestration patters altered. Infill with brick and concrete block. Replacement windows. Lacks architectural distinction.	N	N
	1	17a	5435	W. Fort St.	Roberts Brass Manufacturing Company Building	Ca. 1920	Vernacular	Retains high level of historic integrity, although some openings have been infilled with concrete block, most original window openings and materials are retained.	Y	N
	1	27	5604_5614	W. Fort St.	Commercial	Ca. 1928	Vernacular	Some fire damage. Many of the original openings have been altered with a variety of modern replacement materials. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	27	5616	W. Fort St.	Commercial	Ca. 1918	Vernacular	Original storefronts obscured by modern alterations and materials. Cornice partially removed and remainder clad with modern materials. Lacks architectural distinction.	N	N
	1	26	5626	W. Fort St.	Commercial	Ca. 1915	Vernacular	Retains high level of historic integrity, although the storefront and access door to upper floors have been altered. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	27	5634	W. Fort St.	Commercial	Ca. 1921	Vernacular	Altered storefront and fenestration pattern. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	26	5635	W. Fort St.	Commercial	Ca. 1954	Vernacular	Retains a high level of historic construction materials. Building is typical of those in the area. Lacks architectural distinction.	N	N
	1	27	5644	W. Fort St.	Commercial	Ca. 1957	Vernacular	Two buildings combined into a single storefront through extensive remodeling. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	27	5648	W. Fort St.	Commercial	Ca. 1916	Vernacular	Storefront clad with porcelain enamel metal panels. Altered fenestration pattern. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	27	5658	W. Fort St.	Commercial	Ca. 1922	Vernacular	Storefront altered and fenestration pattern reconfigured. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	27	5674_5676	W. Fort St.	Commercial	Ca. 1900	Vernacular	Modern replacement siding, large awning gives illusion that two original storefronts are one building. Lacks architectural distinction.	N	N
	1	27	5700	W. Fort St.	Commercial	Ca. 1930	Vernacular	Fire ruins.	N	N
	1	26	5705	W. Fort St.	Detroit Savings Bank/ George International Building	Ca. 1920	Neoclassical	Retains a high level of historic construction materials, although there front entry has been replaced with a modern double glass door.	Y	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	29	5803	W. Fort St.	Commercial	Ca. 1941	Vernacular	Storefront has been completely obscured by infill construction, leaving only non-traditional entryways on the side of the building. Lacks architectural significance.	N	N
	1	29	5809	W. Fort St.	Commercial	Ca. 1913	Vernacular	Storefront altered with modern replacement materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	28	5824	W. Fort St.	Commercial	Ca. 1928	Vernacular	Modern construction materials alter building façade. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	29	5833	W. Fort St.	Commercial	Ca. 1952	Vernacular	Replaced windows and doors, façade altered. Lacks architectural distinction.	N	N
	1	28	5840	W. Fort St.	Commercial	Ca. 1930	Vernacular	Storefronts altered, fenestration patterns altered, non-period replacement siding. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	28	5848	W. Fort St.	Commercial	Ca. 1929	Vernacular	Retains a high level of historic construction materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	29	5851	W. Fort St.	Commercial	Ca. 1937	Vernacular	Large addition to former façade, modern replacement materials used to alter storefront fenestration pattern. Lacks architectural distinction.	N	N
	1	28	5852	W. Fort St.	Commercial	Ca. 1927	Vernacular	Storefront altered, fenestration altered, non-period wall materials, replaced windows and doors. Typical of the area. Lacks architectural distinction.	N	N
	1	28	5858	W. Fort St.	Commercial	Ca. 1957	Vernacular	Storefront altered, fenestration altered, replaced windows and doors, non-period building materials. Lacks architectural distinction.	N	N
	1	28	5882	W. Fort St.	Commercial	Ca. 1927	Vernacular	Altered storefronts, extensive fire damage on upper floors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	28	5892	W. Fort St.	Commercial	Ca. 1930	Vernacular	Altered storefronts, extensive fire damage on upper floors. Lacks architectural distinction.	N	N
	1	40	6044	W. Fort St.	Commercial	Ca. 1957	Vernacular	Fenestration altered, some openings filled, replaced windows and doors, some modern replacement siding. Lacks architectural distinction.	N	N
	1	41	6100_6106	W. Fort St.	Commercial	Ca. 1912 - 1919	Vernacular	Altered storefront, replaced windows and doors, modern replacement siding. Lacks architectural distinction.	N	N
	1	41	6110	W. Fort St.	Commercial	Ca. 1920	Vernacular	Storefront altered, fenestration altered, replacement siding. Lacks architectural distinction.	N	N
	1	41	6114	W. Fort St.	Commercial	Ca. 1932	Vernacular	Retains much of the historic construction materials although the storefront has been covered with protective materials. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	41	6118	W. Fort St.	Commercial	Ca. 1910	Vernacular	Storefront altered, upper story fenestration altered. Lacks architectural distinction.	N	N
	1	41	6126	W. Fort St.	Commercial	Ca. 1930	Vernacular	Altered store front fenestration pattern, clad with permastone, upper level also clad with modern materials. Lacks architectural distinction.	N	N
	1	421	6131	W. Fort St.	Commercial	Ca. 1939	Vernacular	Storefront fenestration extensively altered. Lacks architectural distinction.	N	N
	1	41	6132	W. Fort St.	Commercial	Ca. 1915	Vernacular	Retains much of the historic construction materials although the storefront has been covered with protective materials. Lacks architectural distinction.	N	N
	1	41	6134	W. Fort St.	Commercial	Ca. 1915	Vernacular	Storefront altered through application of a stone veneer, large awning on second story dramatically changes original building appearance. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	41	6142_6152	W. Fort St.	Commercial	Ca. 1918	Vernacular	Storefront altered, large awning on second story dramatically changes original building appearance. Lacks architectural distinction.	N	N
	1	42a	6155	W. Fort St.	Commercial	Ca. 1947	Vernacular	Storefront fenestration extensively altered. Lacks architectural distinction.	N	N
	1	47	6205	W. Fort St.	Immanuel Baptist/ First Latin American Baptist Church	Ca. 1900	Vernacular	Retains a high level of historic construction materials, although the large stained glass windows have been altered and lower level windows infilled with glass block.	N	N
	1	47	6221	W. Fort St.	Commercial	Ca. 1921	Vernacular	Retains a high level of original construction materials although some modern materials have been added to the small storefront. Lacks architectural distinction.	N	N
	1	47	6239	W. Fort St.	Commercial	Ca. 1920	Vernacular	Storefront altered and brick veneer applied, second story fenestration altered, replaced windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	47	6245	W. Fort St.	Commercial	Ca. 1920	Vernacular	Storefront altered and brick veneer applied, second story fenestration altered, replaced windows and doors. Lacks architectural distinction.	N	N
	1	47	6251	W. Fort St.	Commercial	Ca. 1920	Vernacular	Storefront altered, replaced windows and doors, modern replacement wall materials. Lacks architectural distinction.	N	N
	1	47	6255	W. Fort St.	Commercial	Ca. 1926	Vernacular	Storefront extensively altered with application of brick veneer and metal overhead door. Second story remains intact. Lacks architectural distinction.	N	N
	1	47	6257	W. Fort St.	Commercial	Ca. 1917	Vernacular	Storefronts altered, second story window openings infilled with concrete block. Lacks architectural distinction.	N	N
	1	49	6348	W. Fort St.	Commercial	Ca. 1925	Vernacular	Retains a high level of original construction materials although some modern materials have been added to the small storefront. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	49	6356	W. Fort St.	Commercial	Ca. 1935	Vernacular	Addition, modern replacement siding, fenestration altered. Lacks architectural distinction.	N	N
	1	49	6364	W. Fort St.	Commercial	Ca. 1948	Vernacular	Modest concrete block building. Lacks architectural distinction.	N	N
	1	59	6426	W. Fort St.	Commercial	Ca. 1920	Vernacular	Extensive alterations to the storefront, including application of brick veneer. Second story retains original materials. Lacks architectural distinction.	N	N
	1	59	6500	W. Fort St.	Commercial	Ca. 1910	Vernacular	DEMOLISHED PER AUGUST 2007 FIELD VISIT. All window and door openings covered with plywood or filled.	N	N
	1	59	6514	W. Fort St.	Commercial	Ca. 1914	Vernacular	Extensive alterations to the storefront, second story has had window openings altered and replacement windows added. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	59	6540	W. Fort St.	Commercial	Ca. 1930	Vernacular	Storefront altered, fenestration altered, replaced doors and windows. Lacks architectural distinction.	N	N
	1	60	6600	W. Fort St.	Commercial	Ca. 1920	Vernacular	Building retains most of its original construction materials and design. Some changes made to the storefront through the application of modern materials. Lacks architectural distinction.	N	N
	1	60	6612	W. Fort St.	Commercial Shelter	Ca. 1957	Vernacular	Modern covered storage building. Lacks architectural distinction.	N	N
	1	60	6620	W. Fort St.	Commercial	Ca. 1920	Vernacular	Altered store front, changes to windows on both storefront and second story. Lacks architectural distinction.	N	N
	1	60	6628	W. Fort St.	Commercial	Ca. 1920	Vernacular	Extensive changes to the storefront, including altered window openings and the application of brick infill. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	60	6632	W. Fort St.	Commercial	Ca. 1925	Vernacular	Replaced windows and doors, replacement wall materials. Lacks architectural distinction.	N	N
	1	60	6638	W. Fort St.	Commercial	Ca. 1914	Vernacular	Storefront altered and fenestration pattern reconfigured. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	60	6642_6646	W. Fort St.	Commercial	Ca. 1926	Vernacular	Modest changes to the storefront, alteration to the fenestration patterns. Lacks architectural distinction.	N	N
	1	60	6666	W. Fort St.	Commercial	Ca. 1935	Vernacular	Storefront altered through extensive use of concrete block. Lacks architectural distinction.	N	N
	1	69	6754	W. Fort St.	Two-Family Flat	Ca. 1920	Vernacular	Enclosed porch, replaced windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	70	6908	W. Fort St.	Olivet Presbyterian/ Old Landmark Church of God in Christ	1913	Vernacular	Retains a high level of historic integrity, although some windows and doors have been altered or infilled with glass block.	Y	N
	1	68	6921	W. Fort St.	Southwestern High School	1915, 1921, 1969	Collegiate Gothic	Retains a high level of historic integrity. Some additions and changes in window and doors have occurred over time.	Y	N
	1	70	6934	W. Fort St.	The Old Landmark C.O.G.I.C. Complex	Ca. 1946	Vernacular	Altered storefront and fenestration pattern. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	70	6954 or 6944	W. Fort St.	Commercial	Ca. 1916	Vernacular	Storefront altered with modern replacement materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	71	7000	W. Fort St.	Commercial	Ca. 1926	Vernacular	Storefronts altered with modern construction materials. Not architecturally or historically distinguished.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	71	7024	W. Fort St.	House	Ca. 1900	T-Plan	Mix of modern replacement wall claddings, alterations to the window fenestration and materials. Lacks architectural distinction.	N	N
	1	72	7033	W. Fort St.	Commercial	Ca. 1950	Vernacular	Storefront altered with modern replacement materials, windows and doors replaced. Lacks architectural distinction.	N	N
	1	71	7034	W. Fort St.	Commercial	Ca. 1910	Vernacular	Retains the original storefront configuration although modern materials have been applied to protect the building. Lacks architectural distinction.	N	N
	1	71	7040	W. Fort St.	Commercial	Ca. 1927	Vernacular	Storefront altered, fenestration altered, glass block window infill. Lacks architectural distinction.	N	N
	1	71	7050	W. Fort St.	Commercial	Ca. 1945	Vernacular	Storefront reconfigured through brick and glass block infill. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	74	7111	W. Fort St.	Commercial	Ca. 1923	Vernacular	Extensive alterations to the building resulting in changes in storefront and fenestration configuration. Lacks architectural distinction.	N	N
	1	74	7139	W. Fort St.	Commercial	Ca. 1957	Vernacular	Storefront altered, fenestration altered. Lacks architectural distinction.	N	N
	1	73	7140	W. Fort St.	Fort Street/Green Street Detroit Police Station	1929	Baroque Elements	Retains a high level of historic integrity. Some additions and changes in window and doors have occurred over time.	Y	N
	1	86	7208	W. Fort St.	Motz's Burgers	Ca. 1956	Commercial Vernacular	Retains a high level of historic integrity.	Y	N
	1	85c	7210	W. Fort St.	Detroit Union Produce Terminal	1929	Art Deco	Retains a high level of historic integrity although some window and doors have been altered over time.	Y	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	86	7238	W. Fort St.	Commercial	Ca. 1957	Vernacular	Altered storefront includes brick infill and glass block windows. Lacks architectural distinction.	N	N
	1	86	7250	W. Fort St.	Commercial	Ca. 1939	Vernacular	Altered storefront includes glass block windows and multiple additions. Lacks architectural distinction.	N	N
	1	87	7420	W. Fort St.	Michigan Bell Telephone Vinewood Dial Office Building	Ca. 1930	Art Deco	Retains a high level of historic integrity although some window and doors have been altered over time.	Y	N
	1	87	7438	W. Fort St.	Commercial	Ca. 1913	Vernacular	Storefront altered, fenestration altered, application of modern replacement materials. Lacks architectural distinction.	N	N
	1	87	7454	W. Fort St.	Commercial	Ca. 1929	Vernacular	Storefront altered, fenestration altered with openings infilled with brick. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	88	7636	W. Fort St.	Commercial	Ca. 1954	Vernacular	Modest concrete block building. Lacks architectural distinction.	N	N
	1	88	7642	W. Fort St.	Residential/ Commercial	Ca. 1923	Vernacular	Storefront altered, fenestration altered, permastone veneer, replaced doors and windows. Lacks architectural distinction.	N	N
	1	88	7660	W. Fort St.	Commercial	Ca. 1909	Vernacular	Fenestration altered, modern replacement siding, mix of original and replaced doors and windows. Lacks architectural distinction.	N	N
	1	88	7666	W. Fort St.	Commercial	Ca. 1890	Vernacular	Extensive alterations through application of modern construction materials and fenestration changes to the storefront. Second story exhibits extensive fire damage. Lacks architectural distinction.	N	N
	1	89	7704	W. Fort St.	Commercial	Ca. 1959	Vernacular	Changes to the façade through modern construction materials and fenestration changes. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	89	7718	W. Fort St.	Commercial	Ca. 1920	Vernacular	Modest building has been altered through modern construction materials and reconfigured fenestration patterns. Lacks architectural distinction.	N	N
	1	89	7750	W. Fort St.	Commercial	Ca. 1957	Vernacular	Modest building retains a high level of its historic materials. Lacks architectural distinction.	N	N
	1	90	7824	W. Fort St.	All Saints Catholic Church Complex	1925 - 1984	Vernacular	Complex includes a church, rectory, convent, garage and marker constructed between 1925 and 1984. Retains a high level of historic integrity.	N	N
	1	85d	7831	W. Fort St.	B & H Sales	Ca. 1915	Vernacular	Most window openings filled or covered, replaced doors, non-period addition. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	39	6017	Gaynor St.	House	Ca. 1911	Foursquare	Vinyl replacement siding, side deck addition, altered front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	39	6023	Gaynor St.	House	Ca. 1910	Foursquare	Vinyl replacement siding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	138	804	Glinnan St.	House	Ca. 1910	Gable Front	Aluminum siding, enclosed front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	137	809	Glinnan St.	House	Ca. 1910	Colonial Revival	Insulbrick siding, modified front porch, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	138	810	Glinnan St.	House	Ca. 1905	Gabled Ell	Combination of Insulbrick and vinyl siding, fire damage. Lacks architectural distinction.	N	N
	1	137	815	Glinnan St.	House	Ca. 1910	Colonial Revival	Aluminum siding, permastone veneer, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	137	829	Glinnan St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	138	830	Glinnan St.	House	Ca. 1910	Gable Front	Aluminum replacement siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	137	835	Glinnan St.	House	Ca. 1910	Colonial Revival	Combination of Insulbrick and aluminum siding, modified fenestration pattern, alterations to the front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	84a	100_120	S. Green St.	Commercial	Ca. 1925	Art Deco Elements	Altered fenestration, replaced windows and doors, additions. Lacks architectural distinction.	N	N
	1	74	162_170	S. Green St.	Commercial	Ca. 1957	Vernacular	Modest concrete block building. Lacks architectural distinction.	N	N
	1	74	186	S. Green St.	Commercial	Ca. 1957	Vernacular	Replaced windows and doors, some window openings filled. Lacks architectural distinction.	N	N
	1	74	196	S. Green St.	Commercial	Ca. 1957	Vernacular	Concrete block building with large addition. Lacks architectural distinction.	N	N
	1	74	216_230	S. Green St.	Commercial	Ca. 1945	Vernacular	Original brick building has large concrete block addition, replacement windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	141	825	N. Green St.	House	Ca. 1910	Gable Front	Exterior clad with T-111 siding, replaced windows and doors, altered front porch, rear addition. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	141	829	N. Green St.	House	Ca. 1905	T-Plan	Vinyl replacement siding, mix of original and replaced windows, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	141	843	N. Green St.	House	Ca. 1910	Cross Gable	Vinyl replacement siding, replaced windows and door, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	114F	205	Harbaugh St.	Commercial	Ca. 1928	Vernacular	Fire damage.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	21	5631	Harvey St.	House	Ca. 1905	Cross Gable	Aluminum siding and permastone veneer, enclosed front and side porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	21	5643	Harvey St.	House	Ca. 1917	Gable Front	Aluminum siding, altered front porch, original front door, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	22	5644	Harvey St.	House	Ca. 1906	Cross Gable	Modified front porch, Insulbrick siding, replaced front door, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	22	5648	Harvey St.	House	Ca. 1943	Cross Gable	Vinyl replacement siding, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	22	5652	Harvey St.	House	Ca. 1880	Cross Gable	Insulbrick siding, front porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	22	5666	Harvey St.	House	Ca. 1918	Cross Gable	Exterior walls are clad with a modern brick veneer and vinyl siding, extensive changes to the front porch. The house is not architecturally or historically distinguished.	N	N
	1	21	5677	Harvey St.	House	Ca. 1910	Gable Front	Insulbrick siding, front porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	53	6327	Holly St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, replaced windows and doors, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	6350	Holly St.	House	Ca. 1906	Cross Gable	Vinyl siding, front porch altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	6356	Holly St.	House	Ca. 1910	Cross Gable/ Queen Anne	Vinyl siding, altered fenestration, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	39	6016	Hussar St.	House	Ca. 1911	Dutch Colonial Revival	Combination of Insulbrick and aluminum siding, altered fenestration, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	39	6022	Hussar St.	House	Ca. 1918	Gable Front	Aluminum replacement siding, front porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	39	6032	Hussar St.	House	Ca. 1905	T-Plan	Exterior walls are clad with a combination of permastone and aluminum siding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	46	6201_1	Hussar St.	Industrial	Ca. 1932	Vernacular	Not architecturally distinctive. Portions of this sprawling complex are vacant and collapsing. Replacement materials, some fire damage.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	13a	4838	W. Jefferson Ave.	Commercial	Ca. 1945	Vernacular	Replaced windows and doors, additions. Lacks architectural distinction.	N	N
	1	18b	5450	W. Jefferson Ave.	Commercial	Ca. 1930	Vernacular	Most window openings filled, some aluminum replacement siding, replaced windows and doors. Lacks architectural distinction.	N	N
	1	20	5654	W. Jefferson Ave.	Commercial	Ca. 1945	Vernacular	Replaced windows and doors. Lacks architectural distinction.	N	N
	1	20	5660	W. Jefferson Ave.	Commercial	Ca. 1945	Vernacular	Replaced windows and doors, additions. Lacks architectural distinction.	N	N
	1	34	5840	W. Jefferson Ave.	Industrial	Ca. 1930	Vernacular	Fenestration pattern altered with glass block window infill. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	37a	6008	W. Jefferson Ave.	Commercial	Ca. 1924	Vernacular	Storefront has an altered fenestration, some replacement windows. Lacks architectural distinction.	N	N
	1	37a	6014	W. Jefferson Ave.	Commercial	Ca. 1928	Vernacular	Extensively altered storefront, rear addition, second story façade remains largely intact. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	43b	6100	W. Jefferson Ave.	Industrial	Ca. 1930	Vernacular	Modest building with some fenestration alterations. Lacks architectural distinction.	N	N
	1	44	6266	W. Jefferson Ave.	Industrial	Ca. 1931	Vernacular	Modern replacement materials. Lacks architectural distinction.	N	N
	1	54	6448	W. Jefferson Ave.	Commercial	Ca. 1890	Vernacular	Combination of vinyl siding and permastone veneer, altered fenestration pattern. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	63b	6666	W. Jefferson Ave.	Commercial	Ca. 1926	Vernacular	Former house-and-canopy gas station and associated concrete block garage. Both buildings have replacement materials. Not architecturally significant.	N	N
	1	65a	6710	W. Jefferson Ave.	Commercial	Ca. 1920	Vernacular	Extensively altered storefront with most openings infilled by modern materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	78a	6970	W. Jefferson Ave.	Industrial	Ca. 1920	Vernacular	Altered fenestration, most openings filled, replaced doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	78a	6982-6986	W. Jefferson Ave.	Kovac's Bar	Ca. 1889	Vernacular	Historically significant. Some integrity issues, but most replacement materials and additions have achieved significance from age. Moderately intact Queen Anne porch.	Y	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	23	138	S. Junction St.	Industrial Complex	Ca. 1945	Vernacular	Multiple additions, altered fenestration, glass block window infill. Lacks architectural distinction.	N	N
	1	25	209	S. Junction St.	House	Ca. 1905	Cross Gable	Vinyl siding, modified porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	25	245	S. Junction St.	House	Ca. 1890	Gabled Ell	Insulbrick siding, most original windows intact, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	25	251	S. Junction St.	House	Ca. 1890	Gabled Ell	Insulbrick siding, most original windows and doors intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	22	300	S. Junction St.	Commercial	Ca. 1940	Vernacular	Modern replacement materials, multiple additions. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	18a	311	S. Junction St.	House	Ca. 1910	Front Gable	Vinyl siding, altered fenestration, replaced windows and door, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	26	321	S. Junction St.	House	Ca. 1890	T-Plan	Insulbrick siding, glass block window infill at basement level, enclosed porch, some replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	26	335 (Rear of 337)	S. Junction St.	House	Ca. 1890	Gable Front	Replacement siding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	26	337	S. Junction St.	House	Ca. 1915	Bungalow	Aluminum siding, enclosed front porch, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	26	341	S. Junction St.	House	Ca. 1915	Bungalow	Permastone veneer, replacement windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	26	349	S. Junction St.	Two-Family Flat	Ca. 1890	Cross Gable	FIRE DAMAGED PER FIELD VISIT JANUARY 2008. Aluminum siding, replaced windows and doors, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	21	414	S. Junction St.	House	Ca. 1900	Gable Front	Insulbrick siding, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	21	430	S. Junction St.	House	Ca. 1900	Gable Front	Well maintained residence with much of its original construction materials. Side porch has been enclosed. Lacks architectural distinction.	N	N
	1	18b	435	S. Junction St.	Two-Family Flat	Ca. 1922	Foursquare	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Insulbrick siding, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18b	463	S. Junction St.	House	Ca. 1900	Gable Front	Replaced windows and doors, replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	18b	503	S. Junction St.	House	Ca. 1904	Gabled Ell	Insulbrick siding, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	16	734	S. Junction St.	Two-Family Flat	Ca. 1914	T-Plan	FIRE DAMAGED OCTOBER 2007. Vinyl siding, extensive alterations to the porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	27	737	S. Junction St.	Commercial	Ca. 1915	Vernacular	Altered storefront openings, some openings have been filled with brick, replaced windows and doors. Lacks architectural distinction.	N	N
	1	16	750	S. Junction St.	House	Ca. 1900	Gable Front	Asbestos siding, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	27	755	S. Junction St.	House	Ca. 1900	Gable Front	Altered façade, enclosed porch addition. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	16	762	S. Junction St.	Two-Family Flat	Ca. 1910	Colonial Revival	Vinyl replacement siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	157	1005	N. Junction St.	Don Graham Funeral Home	Ca. 1950	Vernacular	Some modern replacement siding, replaced windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	155	6006_6008	W. Lafayette Boulevard	Rowhouse	Ca. 1915	Vernacular	Replaced windows and doors, basement level windows covered with plywood, porches altered.	N	Y
	1	155	6016_6018	W. Lafayette Boulevard	Rowhouse	Ca. 1915	Vernacular	Replaced windows and doors, porches altered.	N	Y
	1	155	6022_6028	W. Lafayette Boulevard	Rowhouse	Ca. 1915	Vernacular	Replaced windows and doors, porches altered.	N	Y
	1	155	6034	W. Lafayette Boulevard	Parsonage for Military Evangelical Presbyterian Church	Ca. 1910	Colonial Revival	Some aluminum replacement siding, mix of original and replaced windows and doors. Attached to the Military Evangelical Presbyterian Church by addition, not architecturally significant.	N	N
	1	153	6035_6043	W. Lafayette Boulevard	Commercial	Ca. 1925	Vernacular	Storefront altered with most openings filled with concrete block. Lacks architectural significance.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	155	6051	W. Lafayette Boulevard	Military Avenue Evangelical Presbyterian Church	Ca. 1900	Vernacular	Vinyl replacement siding, retains original stained glass windows and front doors.	Y	N
	1	153	6121_6129	W. Lafayette Boulevard	Rowhouse	Ca. 1915	Vernacular	Replaced windows and doors, porches altered.	N	N
	1	154	6124	W. Lafayette Boulevard	Duplex	Ca. 1890	Vernacular	Replaced windows and doors, glass block window infill. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	151	6200	W. Lafayette Boulevard	Commercial	Ca. 1957	Vernacular	Extensive use of modern replacement materials. Lacks architectural distinction.	N	N
	1	152	6219_6221_6223	W. Lafayette Boulevard	Residential/Commercial	Ca. 1910	Vernacular	Storefronts altered, fenestration altered, some windows broken and/or missing, non-period replacement wall coverings. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	151	6238	W. Lafayette Boulevard	House	Ca. 1905	Vernacular	Combination of vinyl and Insulbrick siding, porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	152	6239_6241	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Retains a high level of original construction materials, only several replacement windows evident. Lacks architectural distinction.	N	N
	1	151	6244	W. Lafayette Boulevard	House	Ca. 1905	Vernacular	Vinyl siding, porch altered, replaced windows and doors, glass block infill in basement window. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	6319_6321	W. Lafayette Boulevard	Duplex	Ca. 1910	Colonial Revival	Some replacement windows, basement level windows infilled with brick and glass block. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	150	6330_6332	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Building retains a high level of its original construction materials. Appears vacant and many windows are boarded for protection. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	150	6336	W. Lafayette Boulevard	House	Ca. 1905	T-Plan	Vinyl siding, modest changes to the porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	6345	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	House retains a high level of its original construction materials. Lacks architectural distinction.	N	N
	1	149	6361	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Wood shingle siding, replaced doors, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	150	6354	W. Lafayette Boulevard	House	Ca. 1905	T-Plan	Insulbrick siding, porch altered, replaced doors, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	6381	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	House retains a high level of its original construction materials. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	CCRG 3	6624_6630	W. Lafayette Boulevard	Rowhouse	Ca. 1915	Vernacular	Most windows and doors replaced, second-story porch altered, original cornice replaced with modern siding. Lacks architectural distinction.	N	N
	1	CCRG 3	6636_6656	W. Lafayette Boulevard	Commercial	Ca. 1955	Vernacular	Altered storefronts with most openings filled or covered, some replaced doors and windows. Lacks architectural distinction.	N	N
	1	145	6705	W. Lafayette Boulevard	Findlater Masonic Temple/ El Bosque Salon	1926 (Sanborn)	Neoclassical	Architecturally and historically significant. Replaced windows.	Y	N
	1	CCRG 1	6900_6906	W. Lafayette Boulevard	Rowhouse	Ca. 1915	Vernacular	Replaced doors and windows, some glass block infill. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	144	6901	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	The brick house has some vinyl siding on the gable ends and shed dormer walls, glass block window infill, some evidence of fire damage. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	144	6925	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Replaced windows and doors, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	CCRG 1	6932	W. Lafayette Boulevard	House	Ca. 1910	Dutch Colonial Revival	Exterior walls are clad with a combination of Insulbrick and vinyl siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	CCRG 1	6938	W. Lafayette Boulevard	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, replaced windows and doors, glass block window infill on basement level. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7003_7005	W. Lafayette Boulevard	Two-Family Flat	Ca. 1915	Vernacular	Building retains a high level of its original construction materials. Lacks architectural distinction.	N	N
	1	142	7009	W. Lafayette Boulevard	House	Ca.1910	Foursquare	Vinyl replacement siding, front porch altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	142	7015	W. Lafayette Boulevard	House	Ca. 1910	Colonial Revival	Combination of Insulbrick and asbestos wall cladding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7021_7023	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Most original windows intact, altered porch areas, replaced doors, some artificial replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7027	W. Lafayette Boulevard	House	Ca. 1910	Gable Front	Aluminum siding in gable peaks. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7033_7035	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Modified porches, some aluminum replacement siding, mix of original and replaced windows and doors.	N	N
	1	142	7039_7041	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	142	7051_7053	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Some vinyl replacement siding, replaced windows and doors, modified porches, rear addition. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7057_7059	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Fenestration altered, most original windows and doors replaced, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7061_7063	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Replaced windows and doors, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7067_7069	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7081	W. Lafayette Boulevard	House	Ca. 1910	Dutch Colonial Revival	Building retains a high level of its original construction materials. The house is typical of those in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	142	7087_7091	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Some window openings covered, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7093_7097	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7105_7107	W. Lafayette Boulevard	Duplex	Ca. 1915	Bungalow	The house retains a high level of its original construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7109_7111	W. Lafayette Boulevard	Duplex	Ca. 1910	Colonial Revival	The building retains a high level of original construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	7115_7117	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, modified front porch areas. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	136	7939	W. Lafayette Boulevard	Commercial	Ca. 1920	Vernacular	Multiple additions have disguised the original layout design of the property. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	160	1007	N. Lansing St.	House	Ca. 1890	T-Plan	Vinyl replacement siding, mix of original and replaced doors and windows, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	160	1013	N. Lansing St.	House	Ca. 1910	Colonial Revival	Vinyl siding, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	161	1016	N. Lansing St.	Two-Family Flat	Ca. 1910	Colonial Revival	Vinyl siding, glass block window infill at basement level, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	160	1019	N. Lansing St.	House	Ca. 1890	Gabled Ell	Vinyl siding and false shutters. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	144	811	Lewerenz St.	House	Ca. 1910	Colonial Revival	Some vinyl siding, replaced windows and doors, some windows broken or missing. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	144	817	Lewerenz St.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	144	823	Lewerenz St.	House	Ca. 1910	Gable Front	Vinyl siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	145	824_826	Lewerenz St.	Two-Family Flat	Ca. 1910	Foursquare	Some vinyl siding, mix of original and replaced windows and doors, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	145	830	Lewerenz St.	House	Ca. 1910	Colonial Revival	Combination of aluminum siding and permastone veneer, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	144	831	Lewerenz St.	House	Ca. 1910	Gable Front	Vinyl siding, porch alterations, most original windows and doors replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	144	839	Lewerenz St.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	146	846_848	Lewerenz St.	Duplex	Ca. 1910	Colonial Revival	Insulbrick siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	144	847	Lewerenz St.	House	Ca. 1910	Vernacular	Vinyl replacement siding, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	145	854_858	Lewerenz St.	Commercial	Ca. 1955	Vernacular	Modest concrete block building with altered fenestration pattern. Lacks architectural significance.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	CCRG 2	1008_1010	Lewerenz St.	Two-Family Flat	Ca. 1910	Colonial Revival	Insulbrick siding, altered fenestration, altered porches, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	45b	131	S. Livernois Ave.	Industrial	Ca. 1925	Vernacular/ Art Moderne	Window openings filled, multiple additions. Lacks architectural distinction.	N	N
	1	51a and 51b	330	S. Livernois Ave.	Industrial	Ca. 1920	Vernacular	Modern replacement materials, multiple additions. Lacks architectural distinction.	N	N
	1	45a	437	S. Livernois Ave.	Abundant Live Aoh Church	Ca. 1920	Vernacular	Some window openings covered, replaced doors and windows, rear addition. Lacks architectural distinction.	N	N
	1	52	520	S. Livernois Ave.	House	Ca. 1915	Gabled Ell	Insulbrick siding, modified front porch, most windows are original, some windows broken and/or missing. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	538	S. Livernois Ave.	House	Ca. 1915	Gabled Ell	Original windows and doors intact, glass block window infill at basement level. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	44	543	S. Livernois Ave.	House	Ca. 1905	Gabled Ell	Insulbrick siding, enclosed porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	544	S. Livernois Ave.	House	Ca. 1915	Cross Gable	Insulbrick siding, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	44	555	S. Livernois Ave.	House	Ca. 1900	Cross Gable	Combination of Insulbrick and vinyl siding, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	44	567	S. Livernois Ave.	House	Ca. 1900	Gable Front	Enclosed porch, modern replacement materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	44	579	S. Livernois Ave.	House	Ca. 1895	Gable Front	Insulbrick siding, enclosed porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	53	626	S. Livernois Ave.	House	Ca. 1910	Cross Gable	Insulbrick siding, glass block infill in basement level windows, replacement windows and doors, altered front porch. Lacks architectural distinction.	N	N
	1	53	632	S. Livernois Ave.	House	Ca. 1918	Bungalow	Insulbrick siding on the dormer walls, most window openings covered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	919_921	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Foursquare	Some vinyl replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	927	N. Livernois Ave.	House	Ca. 1895	Gable Front	Insulbrick siding, replaced front door, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	933	N. Livernois Ave.	House	Ca. 1895	Gabled Ell	Vinyl replacement siding, enclosed porch, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	152	938_940	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Colonial Revival	Second story porch enclosed, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	149	939_941	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Foursquare	House retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	151	1012_1016	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Foursquare	Some replaced doors and windows, modified second-story terrace. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	150	1015	N. Livernois Ave.	House	Ca. 1910	Gable Front	Vinyl replacement siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	151	1018_1022	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Gable Front	Vinyl replacement siding, replaced doors, mix of original and replaced windows, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	150	1021	N. Livernois Ave.	House	Ca. 1910	Colonial Revival	House retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	161	1003	N. McKinstry St.	House	Ca. 1905	Princess Anne	Mix of modern replacement wall materials, mix of original and replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	161	1009_1011	N. McKinstry St.	Two-Family Flat	Ca. 1905	Princess Anne	Aluminum replacement siding, modified porches, replaced windows and doors, side deck addition. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	161	1021	N. McKinstry St.	House	Ca. 1905	T-Plan	Mix of vinyl and modern siding materials, glass block infill windows at basement level, modified porches, mix of original and replaced windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	42b	111	S. Military St.	Industrial	Ca. 1950	Vernacular	Modern replacement materials, some openings filled, multiple additions. Lacks architectural distinction.	N	N
	1	27b	121_131	S. Military St.	Industrial	Ca. 1948	Vernacular	Modern replacement materials, some openings filled, multiple additions. Lacks architectural distinction.	N	N
	1	43a	124	S. Military St.	Industrial	Ca. 1950	Vernacular	Modest concrete block building. Lacks architectural distinction.	N	N
	1	43a	146	S. Military St.	House	Ca. 1910	Cross Gable	Vinyl replacement siding, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43a	152	S. Military St.	House	Ca. 1902	Cross Gable	Insulbrick siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	43a	160	S. Military St.	House	Ca. 1907	Cross Gable	Insulbrick siding, altered front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43a	166	S. Military St.	House	Ca. 1909	T-Plan	Vinyl replacement siding, altered porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37b	189	S. Military St.	House	Ca. 1911	Gable Front	Vinyl replacement siding, altered fenestration, replaced windows and doors. Lacks architectural distinction.	N	N
	1	37b	209	S. Military St.	House	Ca. 1911	Gable Front	Insulbrick siding, enclosed side entry, front porch altered, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43a	218	S. Military St.	Ruins	Ca. 1909	Foursquare	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Fire Ruins.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	43a	226	S. Military St.	Ruins	Ca. 1911	Unknown	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Fire Ruins.	N	N
	1	43b	248	S. Military St.	House	Ca. 1907	Gable Front	Vinyl replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43b	254	S. Military St.	House	Ca. 1912	Gable Front	Aluminum replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37a	259	S. Military St.	House	Ca. 1913	Gable Front	Aluminum replacement siding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43b	260	S. Military St.	House	Ca. 1912	Gable Front	Insulbrick siding. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	27a	265	S. Military St.	House	Ca. 1911	Princess Anne	Vinyl siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	43b	266	S. Military St.	House	Ca. 1912	Gable Front	Exterior walls are clad with a combination of aluminum siding and permastone, modified front porch, mix of original and replaced windows and doors. Lacks architectural distinction.	N	N
	1	37a	277	S. Military St.	House	Ca. 1912	Dutch Colonial Revival	Vinyl siding, front porch altered/enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37a	283	S. Military St.	House	Ca. 1906	Gable Front	Vinyl siding, front porch altered/enclosed, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37a	311	S. Military St.	House	Ca. 1907	Gable Front	NO LONGER EXTANT PER FIELD VISIT AUGUST 2007. Combination of modern exterior wall cladding materials, altered fenestration.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	37a	315	S. Military St.	House	Ca. 1919	Foursquare	Asbestos shingles, altered porches, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	37a	323	S. Military St.	House	Ca. 1910	Foursquare	Includes several outbuildings, modern replacement siding, altered fenestration, mix of original and replaced windows and doors. Lacks architectural distinction.	N	N
	1	41	731	S. Military St.	Two-Family Flat	Ca. 1909	Vernacular	Replaced windows and doors, original cornice removed. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	41	737	S. Military St.	House	Ca. 1895	Colonial Revival	Replacement siding, replaced windows and doors, altered front porch. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	153	831_841	N. Military St.	Rowhouse	Ca. 1915	Vernacular	Some modern replacement siding, modified porches, mix of original and replaced windows and doors.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	154	1007	N. Military St.	House	Ca. 1895	T-Plan	Insulbrick siding, modified front porch, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	155	1012	N. Military St.	House	Ca. 1905	Colonial Revival	Vinyl and aluminum siding, porch enclosed/altered, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	154	1013	N. Military St.	House	Ca. 1915	Bungalow	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	155	1018	N. Military St.	House	Ca. 1905	Colonial Revival	Vinyl siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	14b	110	S. Morrell St.	Industrial	Ca. 1949	Vernacular	Replaced doors and windows, multiple additions. Lacks architectural distinction.	N	N
	1	13b	127	S. Morrell St.	House	Ca. 1910	Gabled Ell	The house retains a high level of historic materials, with the exception of the glass block infill in the basement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	13b	149	S. Morrell St.	House	Ca. 1900	Gabled Ell	Most original windows intact, some openings covered, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18a	186	S. Morrell St.	House	Ca.	Gable Front	FIRE DAMAGED PER FIELD VISIT JANUARY 2008. Mix of original and replaced windows, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18a	208	S. Morrell St.	House	Ca.	Gable Front	Insulbrick siding, fenestration altered, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	18a	216	S. Morrell St.	House	Ca. 1917	Gable Front	FIELD VISIT SEPTEMBER 2007. FIELD VISIT SEPTEMBER 2007. Most original doors and windows intact, modified front porch, some basement windows covered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	13b	217	S. Morrell St.	House	Ca. 1917	Gable Front	The house retains a high level of historic materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18b	230	S. Morrell St.	Two-Family Flat	Ca. 1910	Foursquare	Replaced doors, modified porches, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	13a	233	S. Morrell St.	House	Ca. 1898	Gabled Ell	Porch altered, replaced doors, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18b	238	S. Morrell St.	House	Ca. 1900	Gable Front	Vinyl siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	18b	242	S. Morrell St.	Rowhouse	Ca. 1910	Vernacular	FIRE DAMAGED PER FIELD VISIT AUGUST 2007. Aluminum siding, all window and door openings covered, modified porches.	N	N
	1	13a	247	S. Morrell St.	House	Ca. 1913	Gable Front	Replaced windows and doors, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18b	258	S. Morrell St.	House	Ca. 1910	Gable Front	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Asphalt replacement siding, enclosed front porch, replaced doors and windows. Lacks architectural distinction.	N	N
	1	13a	265	S. Morrell St.	House	Ca. 1912	Gable Front	Some vinyl replacement siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18b	270	S. Morrell St.	House	Ca. 1900	Gable Front	Modified front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	13a	273	S. Morrell St.	House	Ca. 1912	Gable Front	Replaced front door, most original windows intact, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	18b	280	S. Morrell St.	House	Ca. 1890	Cross Gable	Some vinyl replacement siding, rear addition, replaced doors and windows, altered porch. Lacks architectural distinction.	N	N
	1	13a	281	S. Morrell St.	House	Ca. 1912	Gable Front	Aluminum siding, modified front porch, replaced doors, mix of original and replaced doors and windows. Typical of the houses in the area. Lack of architectural distinction.	N	N
	1	18b	290	S. Morrell St.	House	Ca. 1926	Bungalow	Vinyl siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	13a	295	S. Morrell St.	House	Ca. 1912	Gable Front	Vinyl siding, front and side porches altered, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	18b	298	S. Morrell St.	Two-Family Flat	Ca. 1914	Vernacular	Mix of original and replaced doors and windows. Typical of the houses in the area. Lack architectural distinction.	N	N
	1	18b	302	S. Morrell St.	Two-Family Flat	Ca. 1914	Vernacular	Vinyl siding, replaced doors and windows, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	13a	311	S. Morrell St.	House	Ca. 1900	Gable Front	Vinyl siding, rear deck addition, fenestration altered, replaced windows and doors, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	13a	317	S. Morrell St.	House	Ca. 1905	Gable Front	Fire damage, Insulbrick siding, some windows broken or missing, modified front porch. Lacks architectural distinction.	N	N
	1	16	741	S. Morrell St.	House	Ca. 1920	Bungalow	Modern replacement siding, modified front porch, mix of original and replaced doors and windows. Typical of houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	16	747	S. Morrell St.	Two-Family Flat	Ca. 1916	Vernacular	Some modern replacement siding, replaced windows and doors, glass block infill in lower level windows.	N	N
	1	15	750	S. Morrell St.	House	Ca. 1905	Gable Front	Vinyl replacement siding, modified porches, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	16	753	S. Morrell St.	House	Ca. 1900	T-Plan	Aluminum replacement siding, replaced doors and windows, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	15	754	S. Morrell St.	House	Ca. 1880	Gabled Ell	Vinyl replacement siding, altered porch, altered fenestration, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	15	762	S. Morrell St.	House	Ca. 1904	Side Gable/ Princess Anne Elements	Aluminum replacement siding, altered front porch, rear additions. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	159	1011-1017	N. Morrell St.	House	Ca. 1899	Queen Anne	Insulbrick siding, mix of replaced and original windows.	N	N
	1	159	1011-1017	N. Morrell St.	Former Automobile Garage	Ca. 1925	Vernacular	Not architecturally distinctive but does retain historical significance as an automobile repair garage, and as part of property with Queen Anne house.	N	N
	1	160	1012	N. Morrell St.	House/ Former German Spiritual Church	Ca. 1905	T-Plan	Aluminum siding, enclosed front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	159	1023	N. Morrell St.	Two-Family Flat	Ca. 1910	Front Gable	Modern replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	135	7911	Olivet St.	House	Ca. 1910	Gable Front	Most original windows intact, front porch altered, some modern replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	78b	507	S. Post St.	Good Hope Church	1900 (cornerstone)	Vernacular	Steeple removed, replaced doors, no longer associated with original congregation. Lacks architectural distinction.	N	N
	1	78b	511	S. Post St.	Good Hope School/ New Day Multipurpose Community Center	Ca. 1910	Vernacular	Modern façade entry, replaced doors and windows, no longer associated with church. Not architecturally distinctive.	N	N
	1	78b	527	S. Post St.	House	Ca. 1895	Cross Gable	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Insulbrick siding, porch altered, some replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	78b	531	S. Post St.	House	Ca. 1895	Clipped Gable	Insulbrick siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	78b	537	S. Post St.	House	Ca. 1895	Cross Gable	Insulbrick siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	78b	599	S. Post St.	House	Ca. 1915	Dutch Colonial Revival	Insulbrick siding, windows covered. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	78a	605	S. Post St.	Industrial	Ca. 1950	Vernacular	Replacement materials. Lacks architectural distinction.	N	N
	1	78a	659	S. Post St.	Industrial	Ca. 1950	Vernacular	Replacement materials, multiple additions. Lacks architectural distinction.	N	N
	1	78a	667_707	S. Post St.	Industrial	Ca. 1950	Vernacular	Replacement materials, multiple additions. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	57	283	S. Rademacher St.	House	Ca. 1915	Bungalow	Aluminum replacement siding, front porch enclosed, mix of original and replaced windows and doors. Lacks architectural distinction.	N	N
	1	57	295	S. Rademacher St.	House	Ca. 1915	Foursquare	Vinyl replacement siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	57	307	S. Rademacher St.	House	Ca. 1915	Foursquare	Vinyl replacement siding, replaced doors and windows, second-story porch removed, first-story porch altered. Lacks architectural distinction.	N	N
	1	63a	566	S. Rademacher St.	House	Ca. 1919	Cross Gable	Vinyl replacement siding, replaced doors and windows, basement windows filled. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55b	579	S. Rademacher St.	St. Paul A.M.E. Church	Ca. 1928 - 1944 (cornerstones)	Vernacular	Vinyl on dormers, replaced front door, glass block infill in basement windows, altered front porch.	Y	N
	1	63a	596	S. Rademacher St.	House	Ca. 1911	Gable Front	Combination of aluminum siding and permastone veneer, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	55b	603	S. Rademacher St.	House	Ca. 1905	Gable Front	Aluminum replacement siding, altered porches, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63a	608	S. Rademacher St.	House	Ca. 1907	T-Plan	Insulbrick siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55b	609	S. Rademacher St.	House	Ca. 1905	T-Plan	Aluminum siding, altered porches, most original windows and doors intact. Typical of the houses of the area. Lacks architectural distinction.	N	N
	1	63a	612	S. Rademacher St.	House	Ca. 1908	Foursquare	Insulbrick siding, altered fenestration, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55b	615	S. Rademacher St.	House	Ca. 1915	Colonial Revival	Modern siding, permastone veneer, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55a	625	S. Rademacher St.	Two-Family Flat	Ca. 1915	Gable Front	Vinyl siding, modified porches, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	55a	631	S. Rademacher St.	House	Ca. 1905	T-Plan	Vinyl siding, replaced doors and windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55a	637	S. Rademacher St.	House	Ca. 1915	Bungalow	Retains a high level of historic construction materials, although many of the windows have been replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55a	645	S. Rademacher St.	House	Ca. 1905	Cross Gable	Modern replacement siding, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	648	S. Rademacher St.	House	Ca. 1906	T-Plan	Combination of aluminum siding and permastone, replaced doors and windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	654	S. Rademacher St.	House	Ca. 1905	Cross Gable	Insulbrick siding, most original windows intact, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	660	S. Rademacher St.	House	Ca. 1902	T-Plan	Insulbrick siding, modified porch, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	63b	684	S. Rademacher St.	House	Ca. 1905	T-Plan	Insulbrick siding, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	690	S. Rademacher St.	House	Ca. 1905	T-Plan	Insulbrick siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	59	728	S. Rademacher St.	House	Ca. 1910	Vernacular	FIRE DAMAGED PER FIELD VISIT JANUARY 2008. Replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	800	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Vinyl replacement siding, enclosed front porch, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	804	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Some modern replacement wall coverings, most original doors and windows intact, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	810	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Vinyl siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	147	816	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Aluminum siding, fenestration altered, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	824	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Insulbrick siding, altered front porch, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	832	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Combination of vinyl siding and permastone veneer, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	147	840	N. Rademacher St.	House	Ca. 1905	Colonial Revival	Combination of aluminum siding and permastone veneer, modified front porch, mix of original and replaced doors and windows. Lacks architectural distinction.	N	N
	1	147	848_850	N. Rademacher St.	Two-Family Flat	Ca. 1910	Foursquare	Modified rear porches, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	CCRG 4	1000_1002	N. Rademacher St.	Two-Family Flat	Ca. 1910	Foursquare	Modern replacement siding, replaced windows and doors, basement windows infilled, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	CCRG 3	1003	N. Rademacher St.	House	Ca. 1915	Bungalow	Retains a high level of historic construction material. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	33	5840	Reeder St.	House	Ca. 1910	Gable Front	Insulbrick siding, front porch altered, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	33	5850	Reeder St.	House	Ca. 1910	Gable Front	Aluminum siding, front porch altered, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	33	5866	Reeder St.	House	Ca. 1917	Gable Front	Insulbrick siding, some windows broken or missing. Lacks architectural distinction.	N	N
	1	34	5873	Reeder St.	House	Ca. 1910	Princess Anne	Modern replacement wall materials, most original windows intact, replaced doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	34	5879	Reeder St.	House	Ca. 1912	Gable Front	Enclosed front porch, modern wall materials, mix of original and replaced doors and windows. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	33	5880	Reeder St.	House	Ca. 1912	Gable Front	Modern replacement siding, modified front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	34	5887	Reeder St.	House	Ca. 1910	Gable Front	Asbestos shingle wall cladding, most original doors and windows intact, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	56	281	Reid St.	House	Ca. 1910	Gable Front	Aluminum siding, enclosed front porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	57	288	Reid St.	House	Ca. 1910	Gable Front	Vinyl siding, replaced doors and windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	56	295	Reid St.	House	Ca. 1910	Gable Front	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Aluminum siding, most original windows intact, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	56	301	Reid St.	House	Ca. 1908	Gable Front	Asbestos shingle wall cladding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	56	315	Reid St.	House	Ca. 1915	Bungalow	Insulbrick siding, replaced front door, most original windows intact. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	56	NVA, adjacent to 315	Reid St.	House	Ca. 1915	Gable Front	Modern replacement wall materials, replaced doors and windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	54	611	Reid St.	House	Ca. 1919	Gable Front	Vinyl replacement siding, altered front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	54	629	Reid St.	House	Ca. 1911	Gable Front	Vinyl replacement siding, fenestration altered, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55b	638	Reid St.	House	Ca. 1910	Gable Front	Combination of Insulbrick and vinyl wall cladding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	54	645	Reid St.	House	Ca. 1925	Bungalow	Altered front porch, most original doors and windows intact, modern replacement wall materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	55b	652	Reid St.	Two-Family Flat	Ca. 1914	Vernacular	Combination of aluminum siding and permastone veneer, modified front porch, replaced windows and doors, original cornice removed. Lacks architectural distinction.	N	N
	1	55b	660	Reid St.	House	Ca. 1917	Gable Front	Insulbrick siding, most windows and doors replaced, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	54	669	Reid St.	House	Ca. 1918	Foursquare	Combination of asbestos shingles and vinyl siding, replaced doors and windows, glass block infill in lower level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	55a	670	Reid St.	House	Ca. 1909	Gable Front	Insulbrick siding, front porch enclosed, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	54	685	Reid St.	House	Ca. 1917	Gable Front	Mix of modern replacement wall materials, most windows and doors are replacements, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	54	695	Reid St.	Ruins	Ca. 1915	Gable Front	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Fire ruins.	N	N
	1	55a	700	Reid St.	House	Ca. 1915	Colonial Revival	Vinyl replacement siding, most doors and windows are replacements, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	65b	511	Schroeder St.	House	Ca. 1910	Cross Gable	Fire damage.	N	N
	1	66b	518	Schroeder St.	House	Ca. 1910	Cross Gable	Vinyl siding, replaced doors and windows, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	519	Schroeder St.	House	Ca. 1912	Cross Gable	Vinyl replacement siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	525	Schroeder St.	House	Ca. 1916	Gable Front	Vinyl siding, replaced doors and windows, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	66b	532	Schroeder St.	House	Ca. 1910	Cross Gable	Combination of aluminum siding and permastone veneer wall cladding, replaced doors and windows, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	66b	538	Schroeder St.	House	Ca. 1912	T-Plan	Modern replacement wall materials, mix of original and replaced doors and windows, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	551	Schroeder St.	House	Ca. 1905	T-Plan	Vinyl replacement siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	66b	608	Schroeder St.	House	Ca. 1910	Cross Gable	Replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	615	Schroeder St.	House	Ca. 1910	Cross Gable	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Insulbrick siding, replaced doors and windows, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	66a	650	Schroeder St.	House	Ca. 1910	T-Plan	Enclosed side porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	66a	670	Schroeder St.	Apartments	Ca. 1910	Foursquare	Replaced windows and altered front entry. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	140	806	N. Solvay St.	House	Ca. 1910	T-Plan	Combination of asbestos shingles and permastone wall cladding, enclosed front porch, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	139	807	N. Solvay St.	House	Ca. 1910	Princess Anne	Vinyl replacement siding, most windows replaced, enclosed front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	139	815	N. Solvay St.	House	Ca. 1905	Colonial Revival	Aluminum siding, modified front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	816	N. Solvay St.	House	Ca. 1905	Gabled Ell	Vinyl siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	822	N. Solvay St.	House	Ca. 1910	Gable Front	Aluminum siding, replaced doors and windows, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	139	831_833	N. Solvay St.	Two-Family Flat	Ca. 1910	Foursquare	Replaced windows and doors, porches altered, some vinyl replacement siding. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	1	140	838	N. Solvay St.	House	Ca. 1905	Gabled Ell	Vinyl replacement siding, replaced doors and windows, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	63a	507	South St.	House	Ca. 1915	Vernacular	Modern replacement wall materials, replaced windows and doors. Lacks architectural distinction.	N	N
	1	52	6327	South St.	House	Ca. 1905	Gabled Ell	Vinyl siding, mix of original and replaced doors and windows, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	6339	South St.	House	Ca. 1915	Gable Front	Vinyl siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	52	6345	South St.	House	Ca. 1915	Gable Front	Aluminum replacement siding, some replaced windows and doors, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	56	6424	South St.	House	Ca. 1915	Gable Front	Some aluminum replacement siding, porch enclosed, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	75b	7106	South St.	Industrial	Ca. 1945	Vernacular	Modest concrete block building. Lacks architectural distinction.	N	N
	1	91	7430	South St.	House	Ca. 1910	Foursquare	Most windows and doors are replacements, small side addition. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	137	1000	Springwells St.	House	Ca. 1920	Bungalow	Some modern replacement siding, mix of original and replaced doors and windows, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	137	1006	Springwells St.	Residential/ Commercial	Ca. 1915	Colonial Revival	Vinyl replacement siding, porch enclosed, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	137	1020	Springwells St.	Commercial	Ca. 1965 (datestone)	Vernacular	Modern construction. Lacks architectural or historic significance.	N	N
	1	135	NVA	Springwells St.	Commercial	Ca. 1920	Vernacular	Altered façade, replaced windows and doors, glass block infill windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	9a	100	S. Summit St.	Industrial	Ca. 1945	Vernacular	Modest concrete block building. Lacks architectural significance.	N	N
	1	9b	139	S. Summit St.	Industrial	Ca. 1912	Vernacular	Modern replacement materials, some openings filled. Lacks architectural distinction.	N	N
	1	10a	NVA	S. Summit St.	Industrial	Ca. 1957	Vernacular	Modern replacement materials. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	62a	155	S. Waterman St.	Industrial	Ca. 1932	Vernacular	Replaced doors and windows, some former openings filled. Lacks architectural distinction.	N	N
	1	62b	251	S. Waterman St.	Industrial	Ca. 1925	Vernacular	Some former window and door openings covered or filled, glass block infill in some windows, additions. Lacks architectural distinction.	N	N
	1	65b	508	S. Waterman St.	House	Ca. 1917	Foursquare	Mix of original and replaced windows, replaced doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	514	S. Waterman St.	House	Ca. 1909	Gable Front	Insulbrick siding, replaced windows and doors, altered side porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	520	S. Waterman St.	House	Ca. 1909	T-Plan	Vinyl siding, replaced doors and windows, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	63a	547	S. Waterman St.	House	Ca. 1916	T-Plan	Vinyl siding, replaced windows and doors, porch altered, carport addition. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	558	S. Waterman St.	House	Ca. 1910	T-Plan	Asbestos shingle siding, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	564	S. Waterman St.	House	Ca. 1910	T-Plan	Aluminum siding, replaced doors and windows, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63a	579	S. Waterman St.	House	Ca. 1914	Cross Gable	Combination of aluminum siding and permastone veneer, enclosed porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63a	611	S. Waterman St.	House	Ca. 1890	T-Plan	Mix of various replacement sidings, enclosed porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	65b	594	S. Waterman St.	House	Ca. 1890	T-Plan	Insulbrick siding, most original windows intact, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65b	602	S. Waterman St.	House	Ca. 1890	T-Plan	Aluminum siding, porch enclosed, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63a	611	S. Waterman St.	House	Ca. 1900	Gabled Ell	Vinyl siding, porch enclosed, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63a	621	S. Waterman St.	House	Ca. 1917	Gabled Ell	Insulbrick siding, porch altered, replaced doors, most original windows replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63a	629	S. Waterman St.	House	Ca. 1900	Gabled Ell	Vinyl siding, porch altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	63b	637	S. Waterman St.	House	Ca. 1914	Gabled Ell	Combination of vinyl siding and permastone veneer, porch altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	653	S. Waterman St.	House	Ca. 1914	T-Plan	Modern replacement siding, porch enclosed with T-111, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65a	650	S. Waterman St.	House	Ca. 1910	Cross Gable	Vinyl replacement siding, porch enclosed, most original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	677	S. Waterman St.	House	Ca. 1910	Gabled Ell	Insulbrick siding, original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	63b	685	S. Waterman St.	House	Ca. 1914	Gabled Ell	Insulbrick siding, all openings covered. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	65a	698	S. Waterman St.	House	Ca. 1900	Cross Gable	Altered porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	65a	704	S. Waterman St.	House	Ca. 1900	Gabled Ell	Insulbrick siding, altered porch. Common house type in neighborhood, not architecturally or historically significant.	N	N
	1	145	831	N. Waterman St.	Scotten House	Ca. 1865	Gabled Ell	Not architecturally distinctive but does retain historical significance as perhaps the oldest house in the project area. Some window openings have been altered or replaced, porch altered.	N	N
	1	CCRG 2	1003	N. Waterman St.	House	Ca. 1915	Dutch Colonial Revival	Vinyl replacement siding, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	86	730	S. Wheelock St.	House	Ca. 1903	T-Plan	Vinyl siding, enclosed porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	141	810	N. Wheelock St.	House	Ca. 1905	T-Plan	Vinyl siding, rear deck addition, replaced doors and windows, glass block infill in basement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	141	818	N. Wheelock St.	House	Ca. 1905	T-Plan	Aluminum replacement siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	819	N. Wheelock St.	House	Ca. 1905	T-Plan	Aluminum siding, replaced windows and doors, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	141	826	N. Wheelock St.	House	Ca. 1905	T-Plan	Combination of aluminum siding and permastone veneer, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	140	827	N. Wheelock St.	House	Ca. 1915	Dutch Colonial Revival	Vinyl siding, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	141	832_836	N. Wheelock St.	Two-Family Flat	Ca. 1905	Gable Ell	Combination of aluminum siding and permastone veneer, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	835	N. Wheelock St.	House	Ca. 1910	Cross Gable	Combination of Insulbrick siding and permastone veneer, replaced windows and doors, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	140	843	N. Wheelock St.	House	Ca. 1910	Foursquare	Some replacement siding, enclosed porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	1	142	815	Wilde St.	House	Ca. 1905	T-Plan	Aluminum siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	816	Wilde St.	House	Ca. 1910	Foursquare	Some vinyl replacement siding, fenestration altered, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	1	142	819	Wilde St.	House	Ca. 1910	Dutch Colonial Revival	Retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

Tier 2

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	157	5621	Amherst St.	House	Ca. 1905	Gable Front	Aluminum siding, altered front porch, awning additions to façade. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	5637	Amherst St.	House	Ca. 1905	Cross Gable	Vinyl replacement siding, most original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	5645	Amherst St.	House	Ca. 1905	Gable Front	Aluminum replacement siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	5651	Amherst St.	House	Ca. 1905	Gable Front	Combination of vinyl siding and permastone veneer, modified front porch, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	5661	Amherst St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, altered front porch, replacement doors and windows, conversion from single-family home to apartments. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	157	5671	Amherst St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, replacement windows and doors, altered front porch area. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	5821_5825	Amherst St.	Two-Family Flat	Ca. 1910	Vernacular	Some replaced windows and doors, altered porch areas, covered window openings. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	156	5845	Amherst St.	House	Ca. 1895	Gabled Ell	Vinyl siding, original windows, altered porch walls. Typical of the houses in the area. Lacks architectural details.	N	N
	2	156	5851	Amherst St.	House	Ca. 1910	Colonial Revival	Aluminum replacement siding, modified front porch, most original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	5859	Amherst St.	House	Ca. 1910	Colonial Revival	Original windows, modified front porch, glass block infill basement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	156	5871	Amherst St.	House	Ca. 1905	Gable Front	FIELD VISIT SEPTEMBER 2007. FIELD VISIT SEPTEMBER 2007. Artificial siding, modified front porch, foundation covered with pressed tin, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	5881	Amherst St.	Apartments	Ca. 1910	Colonial Revival	Replacement windows and doors, glass block infill in basement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	102	758	Anderson St.	Residential/ Commercial	1905/ 1927	Vernacular	Commercial storefront added 1927 (datestone). May have originally been the Soltesz Bar, before it moved to Dearborn Avenue. Replaced windows and doors, rear addition. Lacks architectural distinction.	N	N
	2	102	802	Anderson St.	House	Ca. 1905	Cross Gable	Mix of original and replaced windows and doors, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	102	810	Anderson St.	House	Ca. 1905	Cross Gable	Insulbrick siding, most original windows and doors intact, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	102	818	Anderson St.	House	Ca. 1905	Cross Gable	Vinyl siding, porch altered, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	101	821	Anderson St.	Commercial	Ca. 1921	Vernacular	Not historically or architecturally distinctive, most doors and windows replaced, others covered.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	112	7806	Bacon St.	House	Ca. 1924	Bungalow	Combination of vinyl and Insulbrick siding, enclosed/altered front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	112	7810	Bacon St.	House	Ca. 1912	Dutch Colonial Revival	Vinyl replacement siding, replaced doors and windows, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7811	Bacon St.	House	Ca. 1910	Gable Front	Vinyl siding, replaced doors and windows, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	112	7816	Bacon St.	House	Ca. 1911	Gable Front	Combination of aluminum siding and permastone veneer, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7817	Bacon St.	House	Ca. 1910	Gable Front	Combination of aluminum and vinyl siding, altered front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	112	7822	Bacon St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	112	7828	Bacon St.	House	Ca. 1910	Gable Front	Vinyl siding, altered front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7845	Bacon St.	House	Ca. 1910	Gable Front	Vinyl siding, altered front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	112	7850	Bacon St.	House	Ca. 1912	Cross Gable	Asbestos shingles, porch altered, most original windows and doors intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7851	Bacon St.	House	Ca. 1910	Gable Front	Aluminum siding, enclosed front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	111	7855	Bacon St.	House	Ca. 1910	Cross Gable	Vinyl siding, altered porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7859	Bacon St.	House	Ca. 1910	Gable Front	Vinyl siding, altered front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	112	7862	Bacon St.	House	Ca. 1910	Cross Gable	Combination of aluminum siding and permastone veneer, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7865	Bacon St.	House	Ca. 1910	Gabled Front	Combination of asbestos and vinyl siding, porch altered, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	112	7868	Bacon St.	House	Ca. 1916	Cross Gable	Vinyl siding, porch altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	112	7874	Bacon St.	House	Ca. 1912	Gable Front	Insulbrick siding, front porch altered, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7875	Bacon St.	House	Ca. 1905	Gable Front	Insulbrick siding, front porch altered, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7885	Bacon St.	Residential/ Commercial	Ca. 1908	Vernacular	Commercial storefront addition, aluminum siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	1019	N. Beard St.	House	Ca. 1915	Bungalow	Side addition, combination of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 1	1024	N. Beard St.	House	Ca. 1910	Gable Front	Aluminum siding, modified front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 1	1030	N. Beard St.	House	Ca. 1910	Gable Front	Combination of Insulbrick and vinyl siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 1	1036	N. Beard St.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 1	1042	N. Beard St.	House	Ca. 1910	Gable Front	Insulbrick siding, altered front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	109a	7901	Burdeno St.	House	Ca. 1905	Gabled Ell	Insulbrick siding, altered front porch, replaced doors and windows, glass block infilled windows at basement level. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	109a	7911	Burdeno St.	House	Ca. 1905	Gabled Ell	Insulbrick siding, altered porch, plywood protects most window and door openings of the vacant building. Lacks architectural distinction.	N	N
	2	109a	7914	Burdeno St.	House	Ca. 1905	Gabled Ell	Vinyl siding, replaced doors and windows, glass block infill in basement windows, enclosed front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	156	1021	N. Campbell St.	House	Ca. 1910	Colonial Revival	Aluminum siding and permastone veneer, modified front porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	1026	N. Campbell St.	House	Ca. 1890	Queen Anne	Some vinyl replacement siding and permastone veneer, modified front porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	1033	N. Campbell St.	House	Ca. 1910	Colonial Revival	Combination of vinyl siding and permastone veneer, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	1034	N. Campbell St.	House	Ca. 1910	Colonial Revival	Some vinyl replacement siding, altered front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	1042	N. Campbell St.	House	Ca. 1910	Colonial Revival	Some aluminum replacement siding, some window openings bricked, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	156	1043	N. Campbell St.	House	Ca. 1895	Gabled Ell	Vinyl replacement siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	1051	N. Campbell St.	House	Ca. 1890	T-plan/ Queen Anne Elements	Combination of vinyl siding and Insulbrick, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	149	1006_1008	N. Casgrain St.	Two-Family Flat	Ca. 1910	Foursquare	Retains a high level of historic construction materials although the dormer window appears to have been replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1014	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1020	N. Casgrain St.	House	Ca. 1910	Foursquare	Replaced windows, porches altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1021	N. Casgrain St.	House	Ca. 1910	Gable Front	Aluminum siding, replacement windows, porches altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1026	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Aluminum replacement siding, front porch removed. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	149	1027	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1032	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Retains high level of historic construction materials, with only modest changes made to the front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1033	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Most of house has been clad with rubble stone permastone, some vinyl siding on soffits. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1038	N. Casgrain St.	Two-Family Flat	Ca. 1910	Foursquare	Building retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	149	1039	N. Casgrain St.	House	Ca. 1910	Colonial Revival	Combination of aluminum siding and permastone veneer, front porch altered, glass block infill in basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name		Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	155	1027	N. Cavalry St.	House	Ca. 1910	Gable Front	Combination of aluminum siding and permastone veneer, modified front porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	1030	N. Cavalry St.	House	Ca. 1905	T-Plan	Combination of aluminum siding and permastone veneer, modified front porch, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	155	1033	N. Cavalry St.	Two-Family Flat	Ca. 1910	Gable Front	Altered front porch and most original windows. Typical of houses in the area. Lacks architectural distinction.	N	N
	2	155	1039	N. Cavalry St.	House	Ca. 1910	Colonial Revival	Combination of aluminum siding and permastone veneer, most original windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	1040	N. Cavalry St.	House	Ca. 1905	T-Plan	Combination of aluminum siding and permastone veneer, modified porch area, glass block infill windows at basement level. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name		Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	155	1045	N. Cavalry St.	House	Ca. 1910	Gable Front	Insulbrick siding, altered front porch, replaced front door, most original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	156	1048	N. Cavalry St.	House	Ca. 1905	T-Plan	Vinyl replacement siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	155	1051	N. Cavalry St.	House	Ca. 1910	Dutch Colonial Revival	Combination of aluminum siding and permastone veneer, mix of original and replaced windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	139	848	N. Central St.	House	Ca. 1905	Cross Gable	Vinyl replacement siding, replaced windows, altered side porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	138	855	N. Central St.	House	Ca. 1910	Dutch Colonial Revival	Exterior walls are clad with Insulbrick siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	138	863	N. Central St.	House	Ca. 1905	Cross Gable	Insulbrick siding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	138	871	N. Central St.	House	Ca. 1905	Cross Gable	Aluminum siding, front porch enclosed, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	139	874	N. Central St.	House	Ca. 1895	T-Plan	Vinyl siding, replaced windows, porch altered/enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	138	879	N. Central St.	House	Ca. 1905	T-Plan	Aluminum siding, most original windows, pressed metal panels over the foundation. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	139	880	N. Central St.	House	Ca. 1910	Colonial Revival	Combination of Insulbrick, permastone veneer and metal siding, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	139	886	N. Central St.	House	Ca. 1910	Colonial Revival	Vinyl siding, modified front porch, glass block infill of basement level windows, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	138	887	N. Central St.	House	Ca. 1895	T-Plan	Aluminum siding, porch modified, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	138	895	N. Central St.	House	Ca. 1895	Gable Front/ Princess Anne	Vinyl siding, modified front porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	3a	140	S. Clark St.	Former Stable/ Car Storage Building	Ca. 1885	Vernacular	Replaced overhead doors, replaced windows, some openings bricked. Lacks architectural distinction.	N	N
	2	3a	174	S. Clark St.	Former Detroit Copper & Brass Rolling Mills Complex	Ca. 1890/ 1906	Georgian Revival/ Monitor Roof Structure	Two buildings are extant, the Georgian Revival office building (1906) and a monitor-roof building (ca. 1890). The office has a few additions and most windows and doors are replaced.	Y	N
	2	CCRG 27	730	S. Clark St.	Apartments	Ca. 1915	Vernacular	Little-altered mid-size apartment building but 760 Campbell Street is a better example of a more high-style, H-shaped apartment building.	N	N
	2	162	1035_1041	N. Clark St.	Houses	Ca. 1910	Colonial Revival	1035 - Vinyl siding and permastone veneer, glass block infill windows, modified front porch. 1041 - Aluminum siding. Neither house exhibits architectural distinction.	N	N
	2	162	1055	N. Clark St.	House	Ca. 1910	Colonial Revival	Combination of aluminum siding and permastone veneer, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	162	1061	N. Clark St.	Duplex	Ca. 1910	Gable Front	Vinyl siding, mix of original and replaced windows, porches altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	82	415_419	Cottrell St.	Two-Family Flat	Ca. 1910	Foursquare	Enclosed rear porches, replaced windows and doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	91	414	Cottrell St.	House	Ca. 1905	Cross Gable	Enclosed front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	91	440	Cottrell St.	Church	1926 (datestone)	Vernacular	Replaced doors and windows, some lower level window openings covered. Lacks architectural distinction.	N	N
	2	81	515	Cottrell St.	House	Ca. 1905	T-Plan	House retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	150	1018	N. Crawford St.	House	Ca. 1905	T-Plan	Combination of asbestos shingles and permastone veneer, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 5	1021	N. Crawford St.	House	Ca. 1910	Dutch Colonial Revival	Combination of aluminum siding and permastone veneer. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	150	1024	N. Crawford St.	House	Ca. 1905	T-Plan	Aluminum siding, replaced windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 5	1027	N. Crawford St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, altered entry porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	150	1030	N. Crawford St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	159	1036	N. Crawford St.	House	Ca. 1905	T-Plan	Vinyl replacement siding, enclosed/altered porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 5	1039	N. Crawford St.	House	Ca. 1910	Foursquare	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	150	1042	N. Crawford St.	House	Ca. 1905	T-Plan	Vinyl siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 5	1051	N. Crawford St.	House	Ca. 1910	Foursquare	Combination of aluminum siding and permastone veneer, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	150	1054	N. Crawford St.	House	Ca. 1905	T-Plan/ Princess Anne	Aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	98	403	Crossley St.	House	Ca. 1905	Cross Gable	Modern siding, enclosed front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	98	409	Crossley St.	House	Ca. 1905	Cross Gable	Modern siding, altered fenestration, awning additions, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	98	427	Crossley St.	House	Ca. 1905	Cross Gable	FIELD VISIT SEPTEMBER 2007. Combination of aluminum siding and permastone veneer, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural	N	N
	2	97	511	Crossley St.	House	Ca. 1905	Cross Gable	Aluminum siding, mix of original and replaced doors and windows, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	97	517	Crossley St.	House	Ca. 1905	Cross Gable	Modern siding, altered porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	97	527	Crossley St.	House	Ca. 1905	Cross Gable	Modern replacement siding, altered porch, rear addition, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	100	742	Crossley St.	House	Ca. 1910	Colonial Revival	Insulbrick siding, enclosed front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	101	800_814	Crossley St.	Industrial	Ca. 1957	Vernacular	Modest concrete block building. Lacks architectural distinction.	N	N
	2	95	815	Crossley St.	House	Ca. 1895	T-Plan	Insulbrick siding, altered front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	95	825	Crossley St.	House	Ca. 1895	T-Plan	Altered porch, replacement siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	154	1026_1030	N. Dragoon St.	Duplex	Ca. 1905	Vernacular	Altered entry porches, replaced windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	151	1029	N. Dragoon St.	House	Ca. 1895	Gabled Ell	Vinyl siding, replaced windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	154	1034	N. Dragoon St.	House	Ca. 1910	Colonial Revival	Vinyl siding, replaced windows and doors, altered front porch. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	151	1035	N. Dragoon St.	House	Ca. 1910	Gable Front	Combination of aluminum siding and permastone veneer, replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	151	1041	N. Dragoon St.	House	Ca. 1910	Colonial Revival	The house retains a high level of its original construction materials, although vinyl siding has been applied to the gable façade and dormer walls. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	160	1020	N. Ferdinand St.	House	Ca. 1910	Dutch Colonial Revival	Aluminum siding, replaced windows and doors, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	159	1021	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Aluminum siding in gable peaks, replaced windows, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1026	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Vinyl siding, replaced windows and doors, modified porch, glass block infill in basement window. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1032	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Replaced windows and doors, glass block infill in basement level window. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	159	1037	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Combination of asbestos and aluminum siding, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	160	1038	N. Ferdinand St.	House	Ca. 1905	Gabled Ell	Aluminum siding, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	159	1041	N. Ferdinand St.	House	Ca. 1910	Gable Front	Brick veneer siding, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1044	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Aluminum siding, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	159	1045_1047	N. Ferdinand St.	Two-Family Flat	Ca. 1910	Foursquare	The house retains a high level of original construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1050	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Vinyl siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	159	1053	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Vinyl siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1056	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Vinyl siding, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	159	1059_1061	N. Ferdinand St.	Two-Family Flat	Ca. 1910	Colonial Revival	Vinyl siding, some replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1062	N. Ferdinand St.	House	Ca. 1910	Colonial Revival	Vinyl siding, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	135	7950	Fisher Freeway W.	House	Ca. 1910	Gable Front	Vinyl siding, large shed dormer addition, some replaced windows and doors, glass block infill in basement level windows, altered porch. Lacks architectural distinction.	N	N
	2	135	7956	Fisher Freeway W.	House	Ca. 1910	Gable Front	Vinyl siding, fenestration altered, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7968	Fisher Freeway W.	House	Ca. 1910	Gable Front	Retains a high level of historic construction materials. Added pressed metal panels over foundation. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7974	Fisher Freeway W.	House	Ca. 1910	Gable Front	Aluminum siding, enclosed front porch, some replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	1	4442	W. Fort St.	Commercial	Ca. 1920	Vernacular	Modern wall cladding, additions, replaced windows and doors, altered fenestration. Lacks architectural distinction.	N	N
	2	CCRG 27	4250	W. Fort St.	Commercial	Ca. 1915	Vernacular	All openings on first story have been filled with concrete block, exterior walls clad with synthetic siding, concrete block addition on rear elevation. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	138	836	Glinnan St.	House	Ca. 1910	Gable Front	The walls are clad with asbestos shingles and Insulbrick, the foundation is clad with pressed metal panels, modified front porch, mix of original and replaced windows. Lacks architectural distinction.	N	N
	2	138	842	Glinnan St.	House	Ca. 1905	Gabled Ell	Vinyl siding, pressed metal over foundation, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	137	857	Glinnan St.	House	Ca. 1910	Gable Front	Combination of vinyl and Insulbrick siding, altered front porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	137	861	Glinnan St.	House	Ca. 1905	Gabled Ell	Aluminum siding, replacement windows and doors, entry porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	137	869	Glinnan St.	House	Ca. 1910	Cross Gable	Walls are clad with aluminum siding and the front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	138	870	Glinnan St.	House	Ca. 1915	Bungalow	Walls are clad with a combination of asphalt shingles and vinyl siding, replaced windows and doors, altered front porch, glass block infill basement windows. Lacks architectural distinction.	N	N
	2	138	870 (Rear)	Glinnan St.	House	Ca. 1920	Gable Front	Walls are clad with a combination of asphalt shingles and Insulbrick siding, replaced windows and doors, altered front porch. Lacks architectural distinction.	N	N
	2	137	871	Glinnan St.	House	Ca. 1915	Bungalow	Walls are clad with a combination of Insulbrick, aluminum, and asphalt shingle siding, porch altered/enclosed, replaced windows and doors. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	82	406	S. Green St.	Two-Family Flat	Ca. 1910	Foursquare	Fire ruins.	N	N
	2	82	412	S. Green St.	Two-Family Flat	Ca. 1910	Foursquare	FIRE DAMAGED PER FIELD VISIT JANUARY 2008. Replaced windows and doors, glass block infill in basement level windows, modified porches. Typical of the houses in the area.	N	N
	2	82	438	S. Green St.	Two-Family Flat	Ca. 1910	Colonial Revival	Aluminum siding, mix of original and replaced windows and doors, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	82	442	S. Green St.	Two-Family Flat	Ca. 1910	Colonial Revival	Some vinyl replacement siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	77b	507	S. Green St.	Two-Family Flat	Ca. 1910	Foursquare	Combination of Insulbrick and aluminum siding, replaced windows and doors, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	81	532	S. Green St.	House	Ca. 1910	Colonial Revival	Altered front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	1003	N. Green St.	House	Ca. 1905	Cross Gable	Vinyl siding, replaced windows, modified entry porch, foundation covered in a mix of artificial materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	1009_1019	N. Green St.	Two-Family Flat	Ca. 1910	Foursquare	Some replacement siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	1021_1023	N. Green St.	Two-Family Flat	Ca. 1910	Foursquare	The house retains a high level of its historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	1031_1033	N. Green St.	Two-Family Flat	Ca. 1910	Foursquare	Combination of Insulbrick and vinyl siding, altered second-story porch, mix of replacement and original windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	141	1037	N. Green St.	House	Ca. 1925	Tudor Revival	Original doors, replacement windows, altered front porch, asphalt shingle siding, aluminum siding in soffits. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	77b	520	Harrington St.	House	Ca. 1910	Gable Front	Insulbrick siding, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	76a	533	Harrington St.	House	Ca. 1910	Gable Front	Combination of aluminum siding and permastone veneer, replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	76a	545	Harrington St.	House	Ca. 1915	Bungalow	Aluminum siding, replaced windows and doors, enclosed front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	77b	546	Harrington St.	Two-Family Flat	Ca. 1910	Foursquare	Insulbrick siding, windows broken and/or missing with many covered by protective plywood, altered front porch. Lacks architectural distinction.	N	N
	2	77b	558	Harrington St.	House	Ca. 1910	Gable Front	Vinyl siding, altered/enclosed front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	76a	593	Harrington St.	House	Ca. 1910	Gable Front	Vinyl siding, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural significance.	N	N
	2	76a	605	Harrington St.	House	Ca. 1895	T-Plan	Combination of Insulbrick and vinyl siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	3b	4468	W. Jefferson Ave.	Detroit Harbor Terminal Building	Ca. 1925	Art Deco	Vacant, some windows and doors missing and/or broken, some fire damage, but otherwise intact. Historically and architecturally significant, recommended eligible.	Y	N
	2	4	4413	W. Jefferson Ave.	Industrial	Ca. 1920	Vernacular	Modest brick warehouse, all W. Jefferson Avenue fenestration infilled. Lacks architectural distinction.	N	N
	2	12a and 12b	5425	W. Jefferson Ave.	Mistersky Power Station Complex/ City of Detroit Public Lighting Commission	Ca. 1926	Vernacular	Several modern structures added to complex, some modern replacement materials.	Y	N
	2	64a	6701	W. Jefferson Ave.	Detroit Edison Delray Powerhouse No. 3	Ca. 1929	Art Deco Elements	Brick powerhouse, all visible openings infilled with brick or other replacement materials.	N	N
	2	95	7600	W. Jefferson Ave.	Detroit Fire Department Engine Company No. 29	Ca. 1907	Vernacular	Historically significant. Replaced windows and doors, lower level windows infilled with glass block, replaced overhead doors. Recommended Eligible.	Y	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	95	7616_7622	W. Jefferson Ave.	Lockeman's Hardware & Boats	Ca. 1918	Vernacular	Hardware/Marine store in business since 1918. Second story replaced windows, storefront modestly altered. Recommended Eligible.	N	N
	2	101	7700_7016	W. Jefferson Ave.	Commercial	Ca. 1905	Vernacular	Partial roof collapse and fire damage evident. Cornice missing, window openings altered, modern replacement materials include permastone, T-111, and aluminum siding.	N	N
	2	109a	7844	W. Jefferson Ave.	Commercial	Ca. 1949	Vernacular	Some glass block infill in the side elevation windows. Typical of the buildings' in the area. Lacks architectural distinction.	N	N
	2	109a	7870	W. Jefferson Ave.	Commercial	Ca. 1932	Vernacular	Some historical significance as a former bank, but alterations have diminished the buildings integrity. Most openings infilled with T-111 or concrete block. Lacks architectural distinction.	N	N
	2	109a	7912	W. Jefferson Ave.	Commercial	Ca. 1957	Vernacular	Modest brick building. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	157	1029	N. Junction St.	House	Ca. 1895	T-Plan	Vinyl siding mix of new and original windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1030	N. Junction St.	House	Ca. 1905	Gable Front	Asbestos shingle siding, modified front porch, rear addition. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	1035	N. Junction St.	House	Ca. 1905	Gable Front	Vinyl siding, altered front porch, mix of new and original windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1038	N. Junction St.	House	Ca. 1905	Gable Front	Vinyl siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	157	1041	N. Junction St.	House	Ca. 1895	Gabled Ell	Vinyl siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	157	1045	N. Junction St.	Rowhouse	Ca. 1915	Vernacular	Replaced windows, modified porch. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	158	1048	N. Junction St.	House	Ca. 1905	Gable Front	Insulbrick siding, some replaced windows and doors, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1054	N. Junction St.	House	Ca. 1910	Colonial Revival	Vinyl siding, altered front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1060	N. Junction St.	House	Ca. 1910	Gable Front	Vinyl siding, replaced windows and doors, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7006	W. Lafayette Boulevard	Apartments	Ca. 1910	Foursquare	Some aluminum siding, replaced windows and doors. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	143	7016_7018	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Some vinyl siding, second-story balcony altered, original doors and windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7024	W. Lafayette Boulevard	House	Ca. 1910	Gable Front	Replaced doors and windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7026_7028	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Some replaced windows and doors, modified second-story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7032_7034	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Mix of original and replaced doors and windows, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7038_7040	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, altered second-story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7050	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Walls are clad with a mix of Insulbrick and aluminum siding, some replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7062	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Front porch enclosed, aluminum replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7066_7068	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Modified porches, original front doors and most original windows intact, some aluminum replacement siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7074	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Aluminum replacement siding, modified front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7080	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7086	W. Lafayette Boulevard	House	Ca. 1910	Foursquare	Some replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7092	W. Lafayette Boulevard	House	Ca. 1910	Colonial Revival	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7098_7100	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, altered second-story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7104	W. Lafayette Boulevard	House	Ca. 1910	Foursquare	Some vinyl replacement siding, enclosed front porch, mix of replacement and original windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7112	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Asbestos shingle siding on the dormers and gable peaks, some replacement windows and doors.	N	N
	2	143	7118	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Vinyl siding, modified front porch, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7124	W. Lafayette Boulevard	House	1910Ca.	Foursquare	Some window openings bricked-in. modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	7223	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Mix of original doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	7253	W. Lafayette Boulevard	House	Ca. 1910	Foursquare	Aluminum siding, modified front porch, some replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	141	7247	W. Lafayette Boulevard	House	Ca. 1915	Bungalow	Parged foundation, glass block infill in the basement level windows, modified porches, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	7244	W. Lafayette Boulevard	House	Ca. 1910	Bungalow	Vinyl replacement siding, enclosed original front porch and new porch addition, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	7233	W. Lafayette Boulevard	Two-Family Flat	Ca. 1910	Colonial Revival	Replaced windows and doors, basement window openings covered, altered second story balcony, some artificial siding. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	7435	W. Lafayette Boulevard	House	Ca. 1910	Foursquare	Replaced windows and doors, some aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	7443_7447	W. Lafayette Boulevard	Two-Family Flat	Ca. 1890	T-Plan	Vinyl siding, shed roof dormer addition on rear ell, altered porches, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	160	1025	N. Lansing St.	House	Ca. 1895	Gabled Ell	Vinyl siding, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	161	1034	N. Lansing St.	House	Ca. 1895	Gabled Ell	Combination of asbestos shingles and vinyl siding, altered front porch, mix of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	161	1040	N. Lansing St.	House	Ca. 1895	Gabled Ell	Insulbrick siding, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1043	N. Lansing St.	House	Ca. 1910	Colonial Revival	Vinyl siding, modified front porches, mix of original and replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	161	1048	N. Lansing St.	House	Ca. 1895	Gabled Ell	Coursed asbestos shingle siding, modified porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	161	1052	N. Lansing St.	House	Ca. 1895	Gabled Ell	Combination of Insulbrick and vinyl siding, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1055	N. Lansing St.	House	Ca. 1895	Gabled Ell	The house retains a high level of its historic construction materials, although the building underwent application of Insulbrick and had the porch enclosed early in its history. Lacks architectural distinction.	N	N
	2	161	1058	N. Lansing St.	House	Ca. 1895	Gabled Ell	Artificial siding, entry porch altered, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	160	1061	N. Lansing St.	House	Ca. 1895	Gabled Ell	Aluminum siding, modified entry porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 1	1013	N. Lewerenz St.	Two-Family Flat	Ca. 1910	Foursquare	Combination of Insulbrick and vinyl siding, altered fenestration, altered front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1016	N. Lewerenz St.	House	Ca. 1910	Princess Anne	Vinyl siding, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1020	N. Lewerenz St.	House	Ca. 1910	Colonial Revival	Vinyl siding, replacement doors and windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 1	1021	N. Lewerenz St.	House	Ca. 1915	Bungalow	Enclosed front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1028	N. Lewerenz St.	House	Ca. 1915	Bungalow	Aluminum siding, incongruous second story addition, altered porch, mix of new and original windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 1	1029	N. Lewerenz St.	House	Ca. 1910	Foursquare	Insulbrick siding, enclosed front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1032	N. Lewerenz St.	House	Ca. 1915	Bungalow	Some vinyl siding, enclosed front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1038	N. Lewerenz St.	House	Ca. 1910	Dutch Colonial Revival	Aluminum siding, enclosed front porch, most windows and doors replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7003	Lexington St.	House	Ca. 1915	Bungalow	Coursed asbestos shingles, replaced windows and doors, some fire damage. Lacks architectural distinction.	N	N
	2	143	7019_7021	Lexington St.	Two-Family Flat	Ca. 1910	Foursquare	Aluminum siding on the dormer walls, mix of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7025	Lexington St.	House	Ca. 1915	Bungalow	Vinyl siding, altered front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7031	Lexington St.	House	Ca. 1915	Bungalow	Vinyl siding, mix of original and replaced doors and windows, second-story dormer altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7037	Lexington St.	House	Ca. 1910	Foursquare	Vinyl siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7041_7043	Lexington St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of its historic construction materials, although there have been modest changes to the second story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7059	Lexington St.	House	Ca. 1910	Dutch Colonial Revival	The brick house has a combination of asphalt shingles and aluminum siding on the gambrel peak and dormer walls. Some replaced doors and windows. Lacks architectural distinction.	N	N
	2	143	7063	Lexington St.	House	Ca. 1915	Bungalow	Some vinyl replacement siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7067_7069	Lexington St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of its historic construction materials, although there have been modest changes to the second story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7073	Lexington St.	House	Ca. 1910	Colonial Revival	Some modern replacement siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7077_7079	Lexington St.	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, second-story balcony altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7085_7087	Lexington St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of its historic construction materials, although there have been modest changes to the second story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7093_7095	Lexington St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of its historic construction materials, although there have been modest changes to the second story balcony. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7099	Lexington St.	House	Ca. 1925	Minimal Traditional	Some modern replacement siding, mix of original and replaced doors and windows, front porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7113	Lexington St.	House	Ca. 1910	Colonial Revival	Some modern replacement siding, front porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	143	7119	Lexington St.	House	Ca. 1915	Bungalow	Exterior walls are clad with clapboard, Insulbrick, aluminum siding, and permastone veneer, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	143	7127_7129	Lexington St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of its historic construction materials, although there has been modern siding applied to the dormer and soffits. Lacks architectural distinction.	N	N
	2	143	7133_7135	Lexington St.	Rowhouse	Ca. 1915	Vernacular	The building retains a high level of its historic construction materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	159	1025_1027	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Colonial Revival	Replaced doors and windows, porch alterations. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	151	1030_1034	N. Livernois Ave.	Two-Family Flat	Ca. 1910	Colonial Revival	Aluminum siding, replaced doors, porches altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	150	1033	N. Livernois Ave.	House	Ca. 1910	Dutch Colonial Revival	The house retains a high level of its historic construction materials. Typical of the houses in the area. The building lacks architectural distinction.	N	N
	2	150	1037	N. Livernois Ave.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	151	1038	N. Livernois Ave.	House	Ca. 1910	T-Plan	Coursed asbestos shingles, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	151	1044	N. Livernois Ave.	House	Ca. 1910	Gable Front	Replaced windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	150	1049	N. Livernois Ave.	House	Ca. 1910	Colonial Revival	Vinyl siding, porches altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	1	738	S. McKinstry St.	Detroit Edison McKinstry Sub-Station	Ca. 1926	Vernacular/ Art Deco	Retains architectural and historical significance, few alterations.	N	N
	2	161	1027	N. McKinstry St.	House	Ca. 1910	Gable Front	Exterior walls are clad with a combination of aluminum siding and permastone veneer, porch modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	162	1028	N. McKinstry St.	House	Ca. 1910	Colonial Revival	Exterior walls are clad with a combination of aluminum siding and permastone veneer, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	161	1033	N. McKinstry St.	Duplex	Ca. 1895	T-Plan	Aluminum siding, front doors replaced, porches altered, glass block infill in basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	162	1034	N. McKinstry St.	House	Ca. 1910	Colonial Revival	Exterior walls clad with a combination of aluminum siding and permastone veneer, porch modified, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	161	1039	N. McKinstry St.	House	Ca. 1895	Gabled Ell	Insulbrick siding, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	162	1040	N. McKinstry St.	House	Ca. 1910	Colonial Revival	Vinyl siding, porch enclosed/altered, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	161	1045	N. McKinstry St.	Two-Family Flat	Ca. 1895	Gabled Ell	Altered porch, some window openings covered, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	161	1057	N. McKinstry St.	House	Ca. 1895	T-Plan	Aluminum siding, glass block infill in basement level windows, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	162	1058_1060	N. McKinstry St.	Two-Family Flat	Ca. 1910	Colonial Revival	Vinyl siding, modified porch, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	82	7217	Melville St.	House	Ca. 1905	Gable Front	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. The house retains a high level of original construction materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	82	NVA (Rear of 7217)	Melville St.	House	Ca. 1905	Gable Front	Currently clad with Insulbrick siding that has subsequently been painted, there is a large addition on the side of the house. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7819	Melville St.	House	Ca. 1910	Gable Front	Vinyl siding, front porch modified, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7827	Melville St.	House	Ca. 1910	Gable Front	The house retains a high level of original construction materials. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	111	7830	Melville St.	House	Ca. 1895	Gabled Ell	Vinyl siding, porch modified, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	111	7840	Melville St.	House	Ca. 1905	Cross Gable	Vinyl siding, porch altered, replaced windows and doors, glass block infill in the basement level windows. Typical of the houses in the area. The building lacks architectural distinction.	N	N
	2	111	7844	Melville St.	House	Ca. 1895	Gabled Ell	Vinyl siding, modified porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7850	Melville St.	House	Ca. 1905	Cross Gable	Vinyl siding, modified porch, replaced windows and doors, glass block infill in the basement level window. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7855	Melville St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, bay window addition, replaced doors and windows, altered fenestration. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	111	7864	Melville St.	House	Ca. 1910	Gable Front	Vinyl siding, front porch altered, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	110	7865	Melville St.	House	Ca. 1905	Gable Front	Vinyl siding, replaced windows and doors, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7875	Melville St.	House	Ca. 1920	Side Gable	Enclosed front porch, some vinyl siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	154	1019	N. Military St.	House	Ca. 1895	T-plan	Aluminum siding, replaced windows and doors, altered entry porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	155	1024	N. Military St.	House	Ca. 1910	Colonial Revival	Vinyl siding, some replaced windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	154	1027	N. Military St.	Two-Family Flat	Ca. 1895	T-plan/ Queen Anne	Aluminum siding, mix of original and new windows and doors, altered porch areas. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	155	1030	N. Military St.	House	Ca. 1910	Foursquare	Aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	154	1033	N. Military St.	House	Ca. 1910	Colonial Revival	Aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	155	1036	N. Military St.	House	Ca. 1910	Colonial Revival	Exterior walls clad with a mix of Insulbrick and aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	154	1041	N. Military St.	House	Ca. 1895	T-plan	Asbestos shingles, replaced windows, altered entry porch, replaced front door. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	155	1042	N. Military St.	House	Ca. 1910	Foursquare	The house retains a high level of historic construction materials. Exceptions include aluminum siding on the dormer and a modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	155	1048	N. Military St.	House	Ca. 1905	Colonial Revival	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	154	1049	N. Military St.	House	Ca. 1910	Colonial Revival	Vinyl siding, modified front porch, glass block infill in the basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	159	1028	N. Morrell St.	House	Ca. 1905	Cross Gable	Shed roof garage addition, vinyl siding, replaced doors and windows, porch modified. Lacks architectural distinction.	N	N
	2	158	1031_1033	N. Morrell St.	Two-Family Flat	Ca. 1905	T-Plan	The house retains a high level of its historic construction materials, with the exception of the Insulbrick siding applied in the early 20th century. Common house type in area. Lacks architectural distinction.	N	N
	2	158	1037	N. Morrell St.	Two-Family Flat	Ca. 1920	Bungalow	Combination of vinyl siding and false stone veneer, modified porches, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1041	N. Morrell St.	House	Ca. 1910	Colonial Revival	Aluminum siding, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	169	1044_1048	N. Morrell St.	Two-Family Flat	Ca. 1910	Foursquare	The house retains a high level of its historic construction materials, with only modest changes made to the porches. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	158	1049_1051	N. Morrell St.	Two-Family Flat	Ca. 1910	Foursquare	Vinyl siding, rear deck addition, altered front porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	159	1052	N. Morrell St.	House	Ca. 1905	Cross Gable	Combination of Insulbrick and aluminum siding, altered front and side porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1055	N. Morrell St.	House	Ca. 1905	Cross Gable	Insulbrick siding, pressed metal panels over front foundation materials, some replaced windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	158	1061_1063	N. Morrell St.	Two-Family Flat	Ca. 1910	Colonial Revival	Vinyl siding, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	150	6331	Musket St.	Ruins	Unknown	Unknown	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Fire Ruins.	N	N
	2	150	6337	Musket St.	House	Ca. 1915	Gable Front	FIRE DAMAGED PER FIELD VISIT SEPTEMBER 2007. Insulbrick and aluminum siding and permastone veneer, porch removed, fire damaged, vacant. Lacks architectural integrity.	N	N
	2	150	6361_6363	Musket St.	Two-Family Flat	Ca. 1915	Gable Front	Insulbrick siding, original doors and windows, with the exception of the glass block infill in the basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	135	7917	Olivet St.	House	Ca. 1910	Gable Front	Vinyl siding, altered porch area, glass block infill in the basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	136	7920	Olivet St.	House	Ca. 1910	Gable Front	Aluminum replacement siding, altered/enclosed front porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7923	Olivet St.	House	Ca. 1910	Cross Gable	Combination of aluminum siding and permastone veneer, altered front porch, most original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	136	7928	Olivet St.	House	Ca. 1910	Gable Front	Insulbrick siding, altered porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7929	Olivet St.	House	Ca. 1910	Gable Front	Insulbrick siding, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	135	7941	Olivet St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, mix of replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	136	7944	Olivet St.	Two-Family Flat	Ca. 1910	Dutch Colonial Revival	Vinyl siding, modified front porch, windows are clad with protective plywood panels. Lacks architectural significance.	N	N
	2	135	7947	Olivet St.	House	Ca. 1910	Gable Front	Altered front porch, vinyl siding, glass block infill in the basement level windows, mix of original and replacement windows and doors. Lacks architectural distinction.	N	N
	2	136	7950	Olivet St.	Two-Family Flat	Ca. 1910	Gable Front	Aluminum siding, altered porches, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7953	Olivet St.	House	Ca. 1910	Gable Front	Vinyl siding, enclosed front porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	136	7956	Olivet St.	House	Ca. 1910	Cross Gable	Aluminum siding, modified front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7959	Olivet St.	House	Ca. 1910	Gable Front	Combination of aluminum and Insulbrick siding, modified front porch, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7965	Olivet St.	House	Ca. 1910	Gable Front	Insulbrick siding, modified front porch, most original windows intact. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7971	Olivet St.	House	Ca. 1910	Gable Front	Combination of vinyl siding and permastone veneer, modified front porch, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	135	7977	Olivet St.	House	Ca. 1910	Gable Front	Exterior walls are clad with T-111, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	136	8032	Olivet St.	House	Ca. 1910	Cross Gable	Aluminum replaced windows, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8035	Olivet St.	House	Ca. 1910	Gable Front	Insulbrick siding, modified front porch, mix of original and replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8039	Olivet St.	House	Ca. 1910	Gable Front	Aluminum siding, enclosed porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	136	8044	Olivet St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, modified front porch, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8045	Olivet St.	House	Ca. 1910	Gable Front	Insulbrick siding, modified front porch, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	134	8051	Olivet St.	House	Ca. 1910	Colonial Revival	Vinyl windows, replaced windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	136	8052	Olivet St.	House	Ca. 1910	Gable Front	Aluminum siding, front porch altered, mix of original and replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8057	Olivet St.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8073	Olivet St.	House	Ca. 1915	Bungalow	Vinyl siding, side addition, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8079	Olivet St.	House	Ca. 1910	Gable Front	Vinyl siding, replaced windows and doors, altered porch area. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	134	8085	Olivet St.	House	Ca. 1910	Gable Front	Coursed asbestos siding with patterned asphalt shingles in the gable peak, front porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	76a	520	S. Post St.	House	Ca. 1895	T-plan	Insulbrick siding, enclosed front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	76a	526	S. Post St.	House	Ca. 1910	Colonial Revival	Some replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	76a	530	S. Post St.	House	Ca. 1910	Gable Front	Insulbrick siding, enclosed front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	76a	556	S. Post St.	House	Ca. 1910	Gable Front	Insulbrick siding, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	76a	584	S. Post St.	House	Ca. 1905	T-Plan	Insulbrick siding, enclosed front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	76b	630	S. Post St.	House	Ca. 1895	T-plan	Vinyl siding, glass block infill in basement level windows, modified porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 4	1008	N. Rademacher St.	House	Ca. 1910	Colonial Revival	Some aluminum replacement siding, modified front porch, replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 4	1014	N. Rademacher St.	House	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1015	N. Rademacher St.	House	Ca. 1915	Bungalow	Mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 4	1020	N. Rademacher St.	House	Ca. 1910	Colonial Revival	Vinyl siding, modified front porch, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1021	N. Rademacher St.	House	Ca. 1910	Foursquare	The house retains a high level of its historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 4	1026	N. Rademacher St.	House	Ca. 1910	Colonial Revival	The house retains a high level of its historic construction materials with only modest changes made to the front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1027	N. Rademacher St.	House	Ca. 1915	Bungalow	The house retains a high level of historic construction materials, the exception being a small amount of vinyl siding on the dormer. Typical of the house in the area. Lacks architectural distinction.	N	N
	2	CCRG 4	1032	N. Rademacher St.	House	Ca. 1910	Foursquare	Vinyl replacement siding, replaced windows and doors, alterations to the front porch. Typical of the houses in the area. Lacks architectural significance.	N	N
	2	CCRG 3	1033_1035	N. Rademacher St.	Two-Family Flat	Ca. 1910	Foursquare	The house retains a high level of historic construction materials. Typical of the house in the area. Lacks architectural distinction.	N	N
	2	CCRG 4	1036_1038	N. Rademacher St.	Two-Family Flat	Ca. 1910	Colonial Revival	The house retains a high level of historic construction materials, the exception being a small amount of vinyl siding on the soffits. Typical of the house in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 3	1039_1041	N. Rademacher St.	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	98	404	S. Solvay St	House	Ca. 1905	Vernacular	Aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	98	428	S. Solvay St	House	Ca. 1905	T-Plan	Vinyl siding, altered fenestration, mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	98	434	S. Solvay St	House	Ca. 1905	Gable Front	Mix of original and replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	97	502	S. Solvay St	Commercial	Ca. 1915	Vernacular	Insulbrick siding, altered storefronts, some windows protected with plywood panels. Lacks architectural distinction.	N	N
	2	97	510	S. Solvay St	House	Ca. 1910	Foursquare	Vinyl siding, mix of original and replaced windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	97	516	S. Solvay St	Two-Family Flat	Ca. 1910	Vernacular	Vinyl siding, mix of original and replaced doors and windows, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	97	544	S. Solvay St	Two-Family Flat	Ca. 1910	Foursquare	Mix of original and replaced doors and windows, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	97	550	S. Solvay St	Two-Family Flat	Ca. 1910	Foursquare	Vinyl siding, mix of original and replaced doors and windows, altered porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	97	564	S. Solvay St	House	Ca. 1910	Vernacular	Insulbrick siding, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	97	588	S. Solvay St	Residential/ Commercial	Ca. 1910	Vernacular	Coursed asbestos shingles, replacement windows and doors. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	97	600	S. Solvay St	Commercial	Ca. 1915	Vernacular	Second story windows replaced, storefront remains intact, but other first story windows protected with plywood panels. Lacks architectural distinction.	N	N
	2	96	730	S. Solvay St	Commercial	Ca. 1915	Vernacular	Modest brick building, most original fenestration is infilled. Lacks architectural distinction.	N	N
	2	96	732	S. Solvay St	Commercial	Ca. 1915	Vernacular	Altered storefront, second story fenestration is intact. Evidence of fire damage on the side elevation. Lacks architectural distinction.	N	N
	2	140	846	N. Solvay St.	House	Ca. 1905	Cross Gable	Aluminum siding, replaced windows, side porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	140	854_856	N. Solvay St.	Two-Family Flat	Ca. 1905	Cross Gable	Exterior walls are clad with T-111 siding, front porch probably removed at site of front façade door, altered side porch. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	139	855	N. Solvay St.	House	Ca. 1895	T-Plan/ Queen Anne	Combination of aluminum siding and permastone veneer, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	139	863	N. Solvay St.	House	Ca. 1895	T-Plan/ Queen Anne	The house retains a high level of its original construction materials. The smooth concrete block foundation suggests it was added after the house was erected. Lacks architectural distinction.	N	N
	2	140	864	N. Solvay St.	House	Ca. 1895	T-Plan	Insulbrick siding, ix of original and replacement windows, side porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	139	871	N. Solvay St.	House	Ca. 1895	T-Plan	Vinyl replaced front door, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	139	879_881	N. Solvay St.	Two-Family Flat	Ca. 1910	Colonial Revival	Vinyl siding, replaced windows and doors, modified porches, glass block infill in basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	140	880	N. Solvay St.	House	Ca. 1895	T-Plan	Vinyl siding, glass block infill in the basement level windows, oriel window addition, porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	109c	7921	South St.	House	Ca. 1925	Tudor Revival	The house retains a high level of historic construction materials. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7812	South St.	House	Ca. 1905	Gable Front	NO LONGER EXTANT PER FIELD VISIT SEPTEMBER 2007. Insulbrick siding, mix of original and replaced doors and windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7822	South St.	House	Ca. 1910	Gable Front	Combination of Insulbrick siding and permastone veneer, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7832	South St.	House	Ca. 1905	Gabled Ell	Aluminum siding, altered porch, some window openings covered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7902	South St.	House	Ca. 1895	T-Plan	Combination of Insulbrick and aluminum siding, mix of original and replaced doors and windows, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	110	7914	South St.	House	Ca. 1910	Colonial Revival	Insulbrick siding, mix of original and replaced doors and windows, some windows broken, missing, or covered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7920	South St.	House	Ca. 1895	T-Plan	Combination of Insulbrick and vinyl siding, most windows and doors replaced, porch altered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	110	7928	South St.	House	Ca. 1895	T-Plan	Insulbrick siding, enclosed porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 3	1008_1010	N. Waterman St.	Two-Family Flat	Ca. 1910	Foursquare	Some modern replacement siding, modified porches. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1009	N. Waterman St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, modified front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1014_1016	N. Waterman St.	Two-Family Flat	Ca. 1910	Foursquare	The building retains a high level of historic construction materials, although both porches have been modified. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1015	N. Waterman St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, replaced windows and doors, glass block infill in basement level windows, modified porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1020_1022	N. Waterman St.	Two-Family Flat	Ca. 1910	Foursquare	Replaced doors and windows, modified second-story porch. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 2	1021	N. Waterman St.	House	Ca. 1915	Side Gable/ Colonial Revival	Replaced windows and doors, altered porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1026_1028	N. Waterman St.	Two-Family Flat	Ca. 1910	Colonial Revival	Fire damage, missing and/or broken windows, altered porches. Lacks architectural distinction.	N	N
	2	CCRG 2	1027	N. Waterman St.	House	Ca. 1915	Bungalow	Aluminum siding, modified front porch, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 2	1035	N. Waterman St.	House	Ca. 1910	Dutch Colonial Revival	Aluminum siding, modified front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1034_1036	N. Waterman St.	Two-Family Flat	Ca. 1910	Colonial Revival	Replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	CCRG 2	1041	N. Waterman St.	House	Ca. 1910	Gable Front	Vinyl siding, replaced doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	CCRG 3	1048_1050	N. Waterman St.	Fourplex	Ca. 1915	Vernacular	Building retains a high level of historic construction material. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	141	844_846	N. Wheelock St.	Two-Family Flat	Ca. 1910	Colonial Revival	Coursed asbestos shingles, some replaced windows, altered front porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	140	851	N. Wheelock St.	House	Ca. 1910	Colonial Revival	Vinyl replacement siding, altered porches, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	856	N. Wheelock St.	House	Ca. 1895	T-Plan	Aluminum siding, replaced windows, altered entry porch, dormer window on rear ell. Typical of the houses in the area. Lacks architectural distinction..	N	N
	2	140	859	N. Wheelock St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl replacement siding, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	141	864	N. Wheelock St.	House	Ca. 1910	Colonial Revival	Combination of aluminum siding and permastone veneer, modified front porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	140	867	N. Wheelock St.	House	Ca. 1905	Cross Gable	The house retains a high level of historic construction materials, with the only change a minor modification to the porch. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	140	875	N. Wheelock St.	House	Ca. 1895	T-Plan	Vinyl replacement siding, porch altered/enclosed, replaced windows, glass block infill in the basement level windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	140	881_883	N. Wheelock St.	Two-Family Flat	Ca. 1910	Foursquare	Combination of aluminum siding and permastone veneer, modified front porch, basement-level windows infilled with brick. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	134	8032_8040	Witt St.	Rowhouse	Ca. 1915	Vernacular	Original cornice removed and area clad with asphalt shingles, modified second-story porches, original windows. Typical of the buildings in the area. Lacks architectural distinction.	N	N
	2	134	8046	Witt St.	House	Ca. 1915	Bungalow	Vinyl siding, modified porch area, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8052	Witt St.	House	Ca. 1915	Bungalow	Aluminum siding, porch enclosed, some windows replaced. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8064	Witt St.	House	Ca. 1915	Bungalow	Aluminum siding, front porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8070	Witt St.	House	Ca. 1910	Gable Front	Aluminum siding, modified porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	134	8076	Witt St.	House	Ca. 1910	Gable Front	Enclosed front porch, currently vacant, fire damage has resulted in broken or missing windows. Lacks architectural distinction.	N	N
	2	133	8083	Witt St.	House	Ca. 1910	Colonial Revival	Combination of Insulbrick and vinyl siding, porch modified, original windows, smooth concrete block foundation suggests it was a later addition. Lacks architectural distinction.	N	N
	2	133	8089	Witt St.	House	Ca. 1910	Gable Front	Aluminum siding, front porch enclosed, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8094	Witt St.	House	Ca. 1910	Gable Front	Front porch altered, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8095	Witt St.	House	Ca. 1910	Gable Front	Aluminum siding, front porch modified, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	134	8100	Witt St.	House	Ca. 1910	Gable Front	Vinyl siding, front porch modified, original front door and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8101	Witt St.	House	Ca. 1910	Gable Front	Vinyl siding, modified front porch, mix of original and replacement doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8106	Witt St.	House	Ca. 1910	Gable Front	Vinyl siding, altered front porch, replacement doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8107	Witt St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, altered front porch, mix of replacement and original doors and windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8113	Witt St.	House	Ca. 1910	Gable Front	Insulbrick siding, original front porch enclosed. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	133	8119	Witt St.	House	Ca. 1910	Gable Front	Vinyl replacement siding, original windows although some openings are covered. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	134	8124	Witt St.	House	Ca. 1915	Bungalow	Combination of vinyl and aluminum siding, modified front porch, foundation covered by artificial siding, replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8131	Witt St.	House	Ca. 1910	Gable Front	Insulbrick siding, altered porch, most windows replaced, original picture window and associated ornamental transom on façade. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8137	Witt St.	House	Ca. 1910	Gable Front	Vinyl siding, modified porch, mix of original and replaced windows. Typical of the houses in the area. Lacks architectural distinction.	N	N
	2	133	8141	Witt St.	House	Ca. 1910	Dutch Colonial Revival	Vinyl siding, modified porch, replacement windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

**Detroit River International Crossing (DRIC)
Above-Ground Survey**

Photo	Tier	DRIC Block No.	Address	Street Name	Property Name	Date	Style	Notes/Comments	NRHP Evaluation	
									Individual	District
	2	133	8155	Witt St.	House	Ca. 1910	Gable Front	Insulbrick siding, enclosed front porch, original windows. Typical of the houses in the area. Lacks architectural distinction.	N	N

Tier 3




A3-1. I-75, View Northwest From Leigh Street



A3-2. Houses along North Side of Thaddeus Street, View Northwest



A3-3. Houses along North Side of Keller Street, View West



A3-4. Two-Story Terraces on Keller Street, View Northwest



A3-5. Streetscape of Harbaugh and Keller Streets, View North



A3-6. Empty Lots on Lyon Street, View Northwest



A3-7. Houses along the North Side of Lyon Street, View Northwest



A3-8. Rear of Houses along the South Side of Melville Street, View
Northeast from Leigh Street




A3-9. House at 8957 Dearborn Street, View Southeast



A3-10. Commercial Buildings along Dearborn Street, View Southeast



A3-11. Houses along the South Side of Melville Street, View Southwest



A3-12. Houses along the South Side of Melville Street, View Southwest



A3-13. Streetscape of House Located on the South Side of South Street,
View Northeast



A3-14. Houses Located along the North Side of Vanderbilt Street, View
Southwest



A3-15. Streetscape of Thaddeus Street, View Southwest



A3-16. Houses Located along the North Side of Thaddeus Street, View West



A3-17. Industrial Development, View South from 844 Harbaugh Street



A3-18. Streetscape of West Jefferson Avenue, View Southwest from Cary Street



A3-19. Multi-Family Dwelling at 710 Sloan Street, View Southwest



A3-20. Delray Community Center on Leigh Street, View Northwest



A3-21. Streetscape of Cobalt Street, View Northwest



A3-22. Streetscape of I-75 and Neighborhood, View North From Leigh Street



A3-23. Streetscape of I-75 and Houses, View North from Leigh Street



A3-24. Streetscape of St. John Cantius Polish Catholic Church and Detroit Wastewater Facility, View Southwest