

Appendix E – Baseline Vibration Monitoring Results (2006)

DRAFT

Figure 1. Vibration Levels from Road Traffic Pass-Bys
House Between 1140 and 1202 Talbot Street






Figure 2. Vibration Levels from Road Traffic Pass-Bys
Sidewalk near the 5th Block South of Riverside Avenue



**Figure 3. Vibration Levels from Road Traffic Pass-Bys
End of Mill Road**



**Figure 4. Vibration Levels from Road Traffic Pass-Bys
Heritage Park Alliance Church**




Figure 5. Vibration Levels from Road Traffic Pass-Bys
Park near 2370 Northway




Figure 6. Vibration Levels from Road Traffic Pass-Bys
Dainty Rice (Ojibway and Broadway)




Figure 7. Vibration Levels from Road Traffic Pass-Bys
Near 4340 Malden




Figure 8. Vibration Levels from Road Traffic Pass-Bys
East side of Huron Church - Opposite to 3495 - Turning Loop






FIGURE 9. VIBRATION TIME HISTORY FOR LOCATION 1




(a) 28 June 2006 – 8.10 am to 8.29 am




(b) 29 June 2006 – 11.32 am to 11.49 am

FIGURE 10. VIBRATION TIME HISTORY FOR LOCATION 2




(a) 28 June 2006 - 9.27 am to 9.47 am




(b) 29 June 2006 - 1.56 pm to 2.10 pm

FIGURE 12. VIBRATION TIME HISTORY FOR LOCATION 4




(a) 28 June 2006 – 11.13 am to 11.31 am




(b) 29 June 2006 – 10.50 am to 11.05 am

FIGURE 13. VIBRATION TIME HISTORY FOR LOCATION 5




(a) 28 June 2006 – 12.09 pm to 12.27 pm




(b) 29 June 2006 – 11.32 am to 11.49 am

FIGURE 15. VIBRATION TIME HISTORY FOR LOCATION 7




(a) 28 June 2006 – 2.06 pm to 2.21 pm




(b) 29 June 2006 – 8.04 am to 8.20 am

FIGURE 16. VIBRATION TIME HISTORY FOR LOCATION 8



(a) 28 June 2006 – 2.49 pm to 3.04 pm



(b) 29 June 2006 – 7.22 am to 7.39 am